

Material Safety Data Sheet
May be used to comply with
OSHA's Hazard Communication Standard,
29 CFR 1910.1200. Standard must be

U.S. Department of Labor Occupational Safety and Health Administration (Non-Mandatory Form)

Form Approved consulted for specific requirements. OMB No. 1218-0072 IDENTITY (As Used on Label and List) Note: Blank spaces are not permitted. If any Item is not applicable, or no Gestetner #621 Ink information is evallable, the space must be marked to indicate that Section 1 Manufacturer's Name **Emergency Telephone Number** Gestetner Manufacturing Limited 01-808-1050 (London) Address (Number, Street, City, State, and ZIP Code) Telephone Number for Information P. O. Box 466, London N17 9LT, England 914-968-6666 Date Prepared September 1986 Signature of Preparer (optional) Section II - Hazardous Ingredients/Identity Information Other Limits Hazardous Components (Specific Chemical Identity; Common Name(s)) OSHA PEL **ACGIH TLV** Recommended % (optional) * Acticide SPX 0.13% 0.03% Pheno l * Made by Thor Chemicals Ltd., Ramsgate Road, Margate, Kent, England Section III - Physical/Chemical Characteristics **Boiling Point** Specific Gravity (H2O = 1) N/A N/A Vapor Pressure (mm Hg) Melting Point N/A N/A Vapor Density (AIR = 1) **Evaporation Rate** N/A N/A (Butyl Acetate = 1) Solubility in Water none Appearance and Odor Oily paste, nearly odorless Section IV — Fire and Explosion Hazard Data Flash Point (Method Used) UEL Flammable Limits LEL N/A Extinguishing Media Foam or gas type. Special Fire Fighting Procedures Ink will not act as a source of ignition, but might burn if involved in a fire. The fumes may contain carbon monoxide and should not be inhaled.

Unusual Fire and Explosion Hazards

none

	Unstable		Conditions to Avoid		
-	Stable	X			
empetibility (Vaterials to Avold)	1 ^_			
			<u> </u>		
zardous Decon	npoeltion or Byprodu	A.13			
zardous lymerization	May Occur	1	Conditions to Avoid		
•	Will Not Occur	Х			
ection VI —	Health Hazard	Data			
oute(s) of Entry:		alation?	Skin?		ingestion?
aith Hazards (Acute and Chronic)				
		<u>n</u>	one		
	NT	D2	LARC Mono	raphs?	OSHA Regulated?
arcinogenicity:					
		. <u></u>			
igns and Symp	toms of Exposure	N/A			
ledical Condition	ons valed by Exposure	N/	Δ		
enerally Aggra	Valed by Exposure				
memency and	First Aid Procedure	93			. •
Bound and	<u></u>	no	ne		
<u></u>		110			
Section VII	— Precautions	for S	ife Handling and Use	no up with VM&P	Nantha or Kerosine.
Section VII	— Precautions ken in Case Materia	for S	ofe Handling and Use based or Spilled Small spills wi		Naptha or Kerosine.
Section VII	— Precautions ken in Case Materia	for S	ife Handling and Use		
Section VII	— Precautions ken in Case Materia	for S	ofe Handling and Use based or Spilled Small spills wi		
Section VII	— Precautions ken in Case Materia pills shovel	for Sal Is Reli	ofe Handling and Use based or Spilled Small spills wi		
Section VII Steps to Be Ta Large S	— Precautions ken in Case Materia pills shovel	for Sal Is Reli	ofe Handling and Use Description Small spills with sawdust and then mop		
Section VII Steps to Be Ta Lange S Waste Disposa	— Precautions ken in Case Materia pills shovel	for Solat is Reliable up w	Small spills wi ith sawdust and then mop waste engine oil.	with Kerosine et	c. Ventilate area.
Section VII Steps to Be Ta Large S Waste Disposa	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli	for Sell up w	Storing A secondary haza	with Kerosine et rd. Do not use	c. Ventilate area. defatting volatile solv
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin.	for Sell up w	Small spills wi ith sawdust and then mop waste engine oil.	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin.	for Sell up w	Storing A secondary haza	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solv
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin.	for Sell up w	Storing A secondary haza	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea Other Precauti	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin.	for Sal Is Relative up we for Use	ife Handling and Use mased or Spilled Small spills wi ith sawdust and then mop waste engine oil. Storing A secondary haza cleansing cream and then	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea Other Precauti	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin. ons none	for Sal is Related up we for Use	ife Handling and Use mased or Spilled Small spills wi ith sawdust and then mop waste engine oil. Storing A secondary haza cleansing cream and then	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea Other Precauti	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin. ons none	for Sal is Related up we for Use	ife Handling and Use mased or Spilled Small spills wi ith sawdust and then mop waste engine oil. Storing A secondary haza cleansing cream and then	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea Other Precauti Section VII Respiratory Pr	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin. ons none II — Control Methodection (Specify Ty) Local Exhaust	for Sal is Related up we for Use	ife Handling and Use mased or Spilled Small spills wi ith sawdust and then mop waste engine oil. Storing A secondary haza cleansing cream and then	with Kerosine et rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea Other Precauti Section VII Respiratory Pr Ventilation N/A	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin. ons none I — Control Methodection (Specify Ty) Local Exhaust Mechanical (Ge	for Sal is Related up we for Use	ife Handling and Use mased or Spilled Small spills wi ith sawdust and then mop waste engine oil. Storing A secondary haza cleansing cream and then	rd. Do not use wash with soap a Y Special Other	c. Ventilate area. defatting volatile solve and water. Store out of
Section VII Steps to Be Ta Large S Waste Disposa Precautions to to clea Other Precauti Section VII Respiratory Pr	— Precautions ken in Case Materia pills shovel Method As Bo Taken in Handli n the skin. ons none I — Control Methodection (Specify Ty) Local Exhaust Mechanical (Ge	for Sal is Related up we for Use	ife Handling and Use mased or Spilled Small spills wi ith sawdust and then mop waste engine oil. Storing A secondary haza cleansing cream and then	rd. Do not use wash with soap a	c. Ventilate area. defatting volatile solve and water. Store out of