

3M General Offices
3M Center
St. Paul, Minnesota 55144-1000
(612) 733-1110

000230

00-11
262

Duns No.: 00-617-3082

MATERIAL SAFETY
DATA SHEET

3M

DIVISION: ADHESIVES, COATINGS AND SEALERS
TRADE NAME: 3M Feathering Disc Adhesive Part Nos. 08041
and 08043
3M I.D. NUMBER: 62-1413-2609-0 62-1413-5509-9
ISSUED: JUNE 30, 1987
SUPERSEDES: MARCH 26, 1986
DOCUMENT: 10-5937-7

1. INGREDIENTS	C.A.S. NO.	PERCENT	EXPOSURE LIMITS
synthetic elastomer	N/A		N/D 5
wood rosins	N/A		N/D 5
TOTAL OF THE ABOVE	N/A	39.0	N/D 5
hexane*	110-54-3	61.0	50 ppm 1
*contains minimum 44% n-hexane	110-54-3		50 ppm 1

SOURCE OF EXPOSURE LIMIT DATA:

1. ACGIH Threshold Limit Values
2. Federal OSHA Permissible Exposure Limit
3. 3M Exposure Guidelines
4. Chemical Manufacturer Recommended Guidelines
5. None Established

ABBREVIATIONS:

N/D - Not Determined
N/A - Not Applicable

2. PHYSICAL DATA

BOILING POINT: 148F Hexane
VAPOR PRESSURE: 126.5 mm @ 68F
VAPOR DENSITY (Air=1): 2.97
EVAPORATION RATE (Ether=1): 1.9
APPEARANCE AND ODOR: Translucent, low viscosity liquid -- strong hexane odor
SOLUBILITY IN WATER: Very slight
SP. GRAVITY (Water=1): 0.78
PERCENT VOLATILE: 61.0%
VISCOSITY: 2,560 Centistokes
PH: N/A

Duns No.: 00-617-3082

MATERIAL SAFETY
DATA SHEETMSDS: 3M Feathering Disc Adhesive Part Nos. 08041 and 08043 Page 2
JUNE 30, 1987

3. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Closed Cup): -10F
FLAMMABLE LIMITS - LEL: 1.2 UEL: 6.9

EXTINGUISHING MEDIA:

CO2, foam, dry chemical

SPECIAL FIRE FIGHTING PROCEDURES:

Fire fighters should be equipped with self-contained breathing apparatus when fighting fires involving this material.

UNUSUAL FIRE AND EXPLOSION HAZARDS:

Extremely Flammable. Overheated, closed containers adjacent to fire could explode due to pressure buildup.

4. REACTIVITY DATA

STABILITY: STABLE

INCOMPATIBILITY - MATERIALS TO AVOID:

N/A

HAZARDOUS POLYMERIZATION, MAY NOT OCCUR

HAZARDOUS DECOMPOSITION PRODUCTS:

CO, CO2 and smoke particles when subjected to excessive heat or flame.

5. ENVIRONMENTAL INFORMATION

SPILL RESPONSE:

Observe precautions in all sections. Extinguish and do not ignite any flame in the immediate work area. Collect spilled material, clean up residue and place in metal container (U.S. Dept. of Transportation approved if material is to be shipped). Use absorbent material as needed in cleanup procedure.

RECOMMENDED DISPOSAL:

Commercial incineration with destruction and removal efficiency greater than 99.99% or reclamation is preferred. Otherwise, dispose in accordance with local and current U.S. Environmental Protection Agency regulations.

ENVIRONMENTAL DATA:

VOC: 475 grams/liter maximum Volatile Organic Compound.

Duns No.: 00-617-3082

**MATERIAL SAFETY
DATA SHEET**MSDS: 3M Feathering Disc Adhesive Part Nos. 08041 and 08043 Page 3
JUNE 30, 1987

=====

6. SUGGESTED FIRST AID

=====

EYE CONTACT:Immediately flush eyes with plenty of water for at least 10 minutes.
Call a physician.**SKIN CONTACT:**

Wash with soap and water.

INHALATION:Provide fresh air. Support or restore breathing if necessary. Call
a physician.**IF SWALLOWED:**Do not induce vomiting. Give two glasses of milk or water to drink.
Call a physician. Do not give liquids to an unconscious person.

=====

7. PRECAUTIONARY INFORMATION

=====

Keep away from heat, sparks and flame. Extinguish and do not ignite
any flame in the immediate work area. The vapors released by this
product can be easily ignited. Use only in areas adequately
ventilated with enough air movement to remove vapors and prevent
vapor buildup. Prevent eye and skin contact. Avoid prolonged
breathing of vapors. Keep container closed when not in use. Keep
out of the reach of children. Wear protective equipment when
handling this product, i.e. chemical goggles or safety glasses and
impervious gloves.

Duns No.: 00-617-3082

MATERIAL SAFETY
DATA SHEETMSDS: 3M Feathering Disc Adhesive Part Nos. 08041 and 08043
JUNE 30, 1987

Page 4

8. HEALTH HAZARD DATA

EYE CONTACT: Liquid may cause severe eye irritation and vapor may cause eye irritation.

SKIN CONTACT: Prolonged or repeated skin contact may defat skin leading to irritation and dermatitis. n-Hexane may be absorbed through the skin in harmful amounts.

INHALATION: Vapor overexposure may cause respiratory system irritation and light-headedness. Repeated or extreme overexposure to n-hexane may cause nervous system damage. Symptoms of overexposure may include headache, dizziness, weakness, fatigue, nausea, loss of coordination and stupor.

INGESTION: May cause digestive system irritation and nervous system impairment. Symptoms include nausea, diarrhea, dizziness, sleepiness, decreased reaction time and slurred speech. Solvent aspiration into the lung as a result of vomiting may cause lung damage and in the extreme, death.

The information on this Data Sheet represents our current data and best opinion as to the proper use in handling of this product under normal conditions. Any use of the product which is not in conformance with this Data Sheet or which involves using the product in combination with any other product or any other process is the responsibility of the user.