Material Safety Data Sheet May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor Occupational Safety and Health Administration (Non-Mandatory Form)

Form Approved



IDCNITIYM 44.44.4	Note: Alegis comments are set and an area
Processed Sand and Gravel	Note: Blank spaces are not permitted. If any item is not applicable, or information is available, the space must be spaced.
Section I	information is available, the space must be marked to indicate the
Manufacturer's Name	I Emorpone Telestra
W.F. Saunders & Sons, Inc.	Emergency Telephone Number (315) 469-3217
Address (Number, Street, City, State, and ZIP Code)	Telephone Number for Information
P.O Drawer-A	
Nedrow. NY 13120	Date Prepared
	3/20/88 Signature of Preparer (optional)
Section II — Hazardous Ingredients/identii	
	· · · · · · · · · · · · · · · · · · ·
Crystalline Silica (Si O ₂ ; quartz	mmon Name(s)) OSHA-PELACGIH-TLVRecommended
crystarrine Strica (St U2; quartz	Total Dust = 30 mg/m ³ /% Quartz + 3
Limestone (Ca CO ₃); calcium carbonate)	Respirable Dust = 10 mg/m³/% Quartz + 2
	mg/m / ~ quit tZ + Z
•	
section III — Physical/Chemical Characteris	ilics
oiling Point NA	Specific Gravity (H ₂ O = 1)
oiling Point NA	Specific Gravity (H ₂ O = 1)
oiling Point NA apor Pressure (mm Hg.)	Specific Gravity (H ₂ O = 1) Melting Point 2.5 to 3.
Section III — Physical/Chemical Characteris oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1)	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate 2.5 to 3.
oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA	Specific Gravity (H ₂ O = 1) Melting Point No. 1
oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Buttl Accrete = 1)
loiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA Diubility in Water Negligible opearance and Odor	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) O
loiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA Diubility in Water Negligible opearance and Odor	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) O
oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA blubility in Water Negligible opearance and Odor Predominately oreay, white and tan angular	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from poudon to cobb.
oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA olubility in Water Negligible opearance and Odor Predominately greay, white and tan angular ection IV — Fire and Explosion Hazard Dat ash Point (Method Used)	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) To rounded particles. No odor. Range in size from powder to cobbilita
loiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA Polubility in Water Negligible peearance and Odor Predominately greay, white and tan angular section IV — Fire and Explosion Hazard Datash Point (Method Used) NA	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from poudon to cobb.
oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA Diubility in Water Negligible opearance and Odor Predominately greay, white and tan angular section IV — Fire and Explosion Hazard Dat ash Point (Method Used) NA tinguishing Media	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from powder to cobbl ta Flammable Limits
loiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA clubility in Water Negligible opearance and Odor Predominately greay, white and tan angular section IV — Fire and Explosion Hazard Date ash Point (Method Used) NA tinguishing Media NA	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from powder to cobbl ta Flammable Limits
loiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA plubility in Water Negligible ppearance and Odor Predominately oreay, white and tan angular ection IV — Fire and Explosion Hazard Dat ash Point (Method Used) NA tinguishing Media	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from powder to cobbl ta Flammable Limits
oiling Point NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA blubility in Water Negligible spearance and Odor Predominately greay, white and tan angular section IV — Fire and Explosion Hazard Date ash Point (Method Used) NA tinguishing Media NA ecial Fire Fighting Procedures NA	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from powder to cobbl ta Flammable Limits
NA apor Pressure (mm Hg.) NA apor Density (AIR = 1) NA blubility in Water Negligible opearance and Odor Predominately greay, white and tan angular ection IV — Fire and Explosion Hazard Dat ash Point (Method Used) NA tinguishing Media NA ecial Fire Fighting Procedures	Specific Gravity (H ₂ O = 1) Melting Point Evaporation Rate (Butyl Acetate = 1) r to rounded particles. No odor. Range in size from powder to cobbl ta Flammable Limits

Section V -	- Reactivity Date	!				
Stability	Unstable		Conditions to Avoid			
	Stable	x				
Incompatibility	(Materials to Avoid)	1				
Hazardous Dec	omposition or Byprodu	None cls		•		
Hazardous	May Occur	Non	Conditions to Avoid			
Polymerization	Will Not Occur	<u> </u>				
O		X				
Section VI Health Hazard Data Route(s) of Entry: Inhalation? Skin? Innestion?						
HOURS, OF EIR	•	rion? Yes	Skin? Yes	Ingestion? Not Normally		
Heelth Hazerds Repeat	(Acute and Chronic) ed and/or prolone	ged co	ontact with skin may cause i			
				ry tract irritation; may cause impairment of lung		
	on and lead to Pi	eumoc	oniosis	•		
Carcinogenicity:	NTP)	IARC M	onographs? OSHA Regulated?		
Signe and Symp	tome of Exposure Pro	longe	d coughing and wheezing; sk	in irritation		
Medical Condition	ins valed by Exposure					
Emergency and	First Aid Procedures	<u></u>				
			ap and water. It irritation re. Administer oxygen as inc	persists, seek medical aid. If breathing becomes icated.		
			Handling and Use			
Steps to Be Tak	en in Case Material la	Releas	ad or Soilled			
Shovel	into original co	ntain	er or waste recepticle. Obs	erve health/repiratory precautions when handling.		
Wasta Diagonal	Mark and					
Waste Disposal		ardou	s waste. Dispose of as an i	ndustrial waste according to local, state, and		
federa	l regulations.		· · · · · · · · · · · · · · · · · · ·			
	e Taken in Handling a			special storage is required.		
- 112 370			THE PROPERTY OF THE	special scorage is required.		
Other Precention	8					
						
Section VIII .	- Control Measu	rec				
Respiratory Prote	ction (Specify Type)					
Not rec	uired under norm	al use	conditions	Special		
	Mechanical (General)			None		
rotective Gloves			. leus			
As requ	As required, industrial fabric type gloves Industrial safety glasses with side shields					
Wear in		k clo	thing and safety footwear.			
Vork/Hygienic Pr						