60100

U.S.A.: Surbond Lubricania inc., P.O. Box 346, & Treadeday Avenue Ma. New York 14020 1.800.387.7070

ANTS Conoda: Surband Lubricants Limited

89 Nipissing Road, Milton, Ontario L91 1R3

RECEIVED MAR 3 1 17 Tet (416) 878-4156 (Wilton) (416) 270-063

	ICA ITEE FROOM	36/-/9/0	<u> </u>			
1	MATERIAL HEALTH AND SAFETY DATA SHEET					
Product SURCUT-190	Chemical Formula Not applicable		· ·			
Other Names						
Emergency Phone No. 800	-387-7970 Name of Contact Carol Clifford					
11.	COMPONENTS listed in the ACGIH TLV Bo	okiet				
		TLV	*			
	Petroleum Oil	5 (mist)	≺95			
[84]	HEALTH HAZARD INFORMATION					
INHALATION	Hot a normal inhalation hazard. Prolonged		e to			
	nigh levels of mist may cause irritation.					
EYE CONTACT	Contains surface active and alkaline material, will cause irritation upon contact.					
SKIN CONTACT	Prolonged or repeated contact with concentrate may cause skin irritation.					
INGESTION _	Not normally a form of exposure, but ingesticause irritation and possible indigestion. I toxicity.	ion will	l l			
v.	HANDLING PRECAUTIONS					

ir splash-proof safety goggles or a face shield. If product is frequely splanhed, wear chemical resistant gloves, apron and footwear to cover areas. If mists are involved at high concentrations, wear an air rator, provide ventilation or use appropriate anti-misting additives

(Include recommendations for personal protective equipment and controls)

•		- 5 0 (.0	1-51 3-083
V. *		PH	E AND EX	PLOSION DATA	
Soding Point Not appl	icable	Flashpoint 174°C COC (345°F		Flammable Limits Not determined	LEL UEL Rat determine
		£	REACT	TVITY	
-					T
STABLE [XX UNS	,— -	LYOPOCIA	US DECOMPOSITION	INCOMPATIBILITY
List conditions t	-	Mary Mary	(List)		(List materials to avoid)
extrem		<u>);</u>	S _{pi} , Ban	sides of C, Na, Ca,	strong scide and oxidizers
		EMERGENCY A	ND FIRE F	GHTING PROCEDUR	E
tight as an	oil fit	re, Respira carbon diox	tors requide to ex	ired. Use water tinguish fire,	r fog, mist, dry
VI.	epu t	CE CLEAN III		TE DISPOSAL PROCEI	
ils, and r	emainder	aubiected	taws, Li	disposal area for quids should be ficient industriant of the dispose	treated to separate
11.			FIRST	AID	
NHALATION	If wor irrits	ker feels d tion persis	iscomfor: t consult	t, remove to fre t a physician.	sh sir. Should
YES	Flush irrita	with water tion persis	for 15 mi	in. Seek medica	1 ettention if
KIN	Wash wo	ith mild song before re	ap and wa	ter. Remove an	d launder contaminate
GESTION		induce vom: Seek medic ion persisa		material may as tion and use st	spirate into the omach lavage if
n.		ĒT/	ALCE DISC		
ore in a duns. Shou was. Shou w before u	ry cool ld produ sing, R	area, Do N	ot press	RUCTIONS urize drum, Do F arm slowly to ro gerous substance	lot cut or weld empty
,	•				
DECEM	3ER 23	1985			
	The same of a large star of	T .		Signed (a	wel Chilland