



MATERIAL SAFETY DATA SHEET

Identity  
Duncan Bisq Stain Opaques OS-400 Series

MSDS # 036

SECTION I

Manufacturer's Name  
Duncan Enterprises  
Address  
5673 E. Shields Ave.  
Fresno, CA 93727

Emergency Telephone Number  
(303) 623-4884  
Telephone Number  
(209) 291-4444  
Date Prepared August 1987  
Prepared By Curt Sathre

Revised

SECTION II  
HAZARDOUS INGREDIENTS

Hazardous Components  
none  
Other Information  
none

OSHA PEL ACGIH TLV CAS # X

SECTION III  
PHYSICAL DATA

Boiling Point, (DEG F)  
212 F  
Melting Point, (DEG F)  
N/A  
Specific Gravity (Water=1):  
1.3  
Appearance And Odor  
Opaque-colored latex paint  
pH  
n/a

Vapor Pressure, (MM HG.)  
n/a  
Vapor Density (AIR=1)  
n/a  
Water Solubility, %  
Insoluble  
Freezing Point  
n/a  
Evaporation Rate (Butyl Acetate=1)  
n/a

SECTION IV  
FIRE AND EXPLOSION HAZARD DATA

Flash Point (Method Used)  
n/a  
Extinguishing Media  
n/a  
Special Fire Fighting Procedures  
None. Will not burn.  
Unusual Fire And Explosion Hazards  
None.

Flammable Limits  
LEL n/a UEL n/a

SECTION V  
REACTIVITY DATA

Stability Unstable: Stable: X

Conditions To Avoid

Incompatibility (Materials To Avoid)

Hazardous Decomposition or Byproducts

Hazardous Polymerization

May Occur:

Will Not Occur: X

Conditions To Avoid

n/a

**SECTION VI**  
**HEALTH HAZARD DATA**

MSDS 036

Routes Of Entry      Inhalation? no      Skin? no      Ingestion? yes

Health Hazards (Acute and Chronic)  
None. Nontoxic

Carcinogenicity      NTP? no      IARC Monographs? no      OSHA Regulated? no

Signs And Symptoms of Exposure  
n/a

Medical Conditions Generally Aggravated by Exposure  
Abrasive, can scratch eyes.

Emergency And First Aid Procedures

Eye contact: Flush with water at least 15 minutes.

Skin contact: Wash with soap and water.

**SECTION VII**  
**PRECAUTIONS FOR SAFE HANDLING**

Steps To Be Taken In Case Material Is Released Or Spilled  
Clean up properly with paper towels and a wet sponge.

Waste Disposal Method  
Put paper towels in trash and rinse out sponge.

Precautions To Be Taken In Handling And Storing  
Keep container sealed.

Other Precautions  
n/a

**SECTION VIII**  
**CONTROL MEASURES**

Respiratory Protection (Specify Type)  
If spraying, do not inhale mist. Use respirator that is NIOSH approved for sprays and mists.

Ventilation

Local Exhaust Recommended	Special Use respirator when spraying
Mechanical (General) Recommended when spraying	Other none
Protective Gloves no	Eye Protection yes

Other Protective Clothing Or Equipment  
None needed

Work/Hygienic Practices  
Good hygiene practices should be followed.

**SECTION IX**  
**ADDITIONAL INFORMATION**

CALIFORNIA Proposition 65      n/a



\*Products bearing the AP Approved Product Seal of The Art and Craft Materials Institute, Inc. are certified in a program of toxicological evaluation by a medical expert to contain no materials in sufficient quantities to be toxic or injurious to humans or to cause acute or chronic health problems. This program is reviewed by the Institute's Toxicological Advisory Board. These products are certified by the Institute to be labeled in accordance with the voluntary chronic hazard labeling standard ASTM D-4236. In addition, there is no physical hazard as defined within 29 CFR Part 1910.1200(c).

**DISCLAIMER** -- Information presented herein has been compiled from sources considered to be dependable and is accurate and reliable to the best of our knowledge and belief but is not guaranteed to be so. Since conditions of use are beyond our control, we make no warranties, expressed or implied, except those that may be contained in our written contract of sale or acknowledgement.