

SB41160 SB41163 SB41166
 SB41161 SB41164 SB41167
 SB41162 SB41165

3637.

Material Safety Data Sheet
 May be used to comply with
 OSHA's Hazard Communication Standard,
 29 CFR 1910.1202. Standards must be
 consulted for specific requirements.

U.S. Department of Labor
 Occupational Safety and Health Administration
 (Non-Mandatory Form)
 Form Approved
 OMB No. 1218-0072



IDENTITY (As Used on Label and List)

GLUE STICKS

Note: Blank spaces are not permitted. If any data is not applicable, or no information is available, the space must be marked to indicate that.

Section I

Manufacturer's Name MONROSE COLORS INC.	Emergency Telephone Number 800 943 0031
Address (Number, Street, City, State, and ZIP Code) 20W201 101ST ST. UNIT F LEMONT, IL. 60439	Telephone Number for Information (SAME)
	Date Prepared 10/01/05
	Signature of Preparer (Typed) [Signature]

Section II -- Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity; Common Name(s))	OSHA PEL	ACGIH TLV	Other Limits Recommended	to (specify)
(NONE)				
POLYVINYL ALCOHOL 65%				
WATER 34.5%				
PIGMENT 1%				

Section III -- Physical/Chemical Characteristics

Boiling Point OVER 212°F		Specific Gravity (H ₂ O = 1)	
Vapor Pressure (mm Hg)	N/A	Melting Point	N/A
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A
Solubility in Water SOLUBLE			
Appearance and Color SEMI-SOLID STICK; ODORLESS			

Section IV -- Fire and Explosion Hazard Data

Flash Point (Method Used) N/A	Flammable Limits	LEL	UEL
Extinguishing Media			
Special Fire Fighting Procedures N/A			
Unusual Fire and Explosion Hazards N/A			

RECEIVED
 OSHA 174, Sept. 1982
 MAR 3 2009
 Facilities Management
 HEALTH AND SAFETY

Section V -- Reactivity Data

Stability	Unstable	Conditions to Avoid
	Stable	

Incompatibility (Materials to Avoid)

Section VI -- Health Hazard Data

Routes of Entry: Inhalation? Skin? Ingestion?

Health Hazards (Acute and Chronic) N/A

Carcinogenicity: NTP? IARC Monographs? OSHA Regulated?

Signs and Symptoms of Exposure N/A

Medical Conditions Generally Aggravated by Exposure N/A

Emergency and First Aid Procedures N/A

Section VII -- Precautions for Safe Handling and Use

Steps to be Taken in Case Material is Released or Spilled

WIPE OFF EXCESS WITH DAMP TISSUE OR CLOTH

Waste Disposal Method N/A

Precautions to be Taken in Handling and Storing N/A

Other Precautions

Section VIII -- Control Measures

Respiratory Protection (Specify Type) N/A

Ventilation	Local Exhaust	Special
	Mechanical (General)	
Protective Gloves	<u>N/A</u>	Other
Other Protective Clothing or Equipment	<u>N/A</u>	Eye Protection

Washhygiene Practices N/A