



QR. INC.

691 WALT WHITMAN RD., MELVILLE, NY 11747 • NY 516 673-7011 • TOLL FREE 800-645-7013 • FAX: 516-673-7013

QUIK-ROK* FAST-SETTING ANCHORING CEMENT

SECTION II: HAZARDOUS	NGREDIENTS					
INGREDIENT Calcium Sulfate Dihydrate CAS #10101414	NTP/LARC/ OSHA CARC. No	PERCENT 90	PPM 10	TLV mg/M²	LEL NA	VAPOR PRESSURE NA

SECTION III: PHYSICAL DATA	
BOILING RANGE NA	VAPOR DENSITY CHEAVIER

☐ LIGHTER, THAN AIR

EVAPORATION CI FASTER CI SLOWER THAN ETHER RATE

PERCENT VOLATILE BY VOLUME

WEIGHT PER GALLON 19.3 Lbs.

SECTION IV: FIRE AND EXPLOSION DATA

DOT Category: Non-Flammable Flash Poi Extinguishing Media: NA Special Firefighting Procédures: NA Unusual Fire & Explosion Hazards: NA NA NA Hazardous Decomposition Products:

Flash Point:

NA

NA

FAX: 516-673-7013 TOLL-FREE: 1-800-645-7013

SEE OTHER SIDE

SECTION V: HEALTH HAZARD DATA

Effects of Overexposure

Eyes

Can cause irritation, redness, tearing,

blurred vision.

Skin

Can cause irritation, burns.

ilds occasionally, get medical attention.

First Aid

Thoroughly wash exposed area with soap and water. Remove contaminated clothing. Launder contaminated

Flush with large amounts of water, lifting upper and lower

clothing before re-use.

Initalation

Can cause injury to lungs.

Keep person warm, quiet and get medical attention.

ingestion

Can cause gastrointestinal irritation.

Do not induce vomiting, keep person warm, quiet, and

get medical attention.

SECTION VI: REACTIVITY DATA

Hazardous Polymerization:

Cannot occur.

Stability: Stable

incompatibility:

Avoid contact with acid minerals.

SECTION VII: SPILL OR LEAK PROCEDURES

Steps to be Taken in Case Material is Released or Spilled

Small Spill: Clean up by use of dustiess methods.

Waste Disposal Method: Dispose of in accordance with local, state and federal regulations.

SECTION VIII: SPECIAL PROTECTION INFORMATION

Respiratory Protection: Niceh/Mesa respirator (dust filter type in compliance with OSHA Std. 29 CER 1910.134). Ventilation: Provide sufficient mechanical (general) and/or local exhaust ventilation to maintain exposure below TLV's.

Protective Gloves: Wear resistant gloves such as Buna-N.

Eye Protection: Chemical spiash goggles in compliance with OSHA regulations are advised.

Other Protective Equipment: Tonravent repeated or prolonged skin contact wear impervious ciothing and boots.

SECTION IX: SPECIAL-PI CAUTIONS

May cause severe skin irritation ϵ burns on individuals with sensitive skin. All hazard precautions given in this data sheet must be observed. Keep out of reach of children.

The information accumulated herein is believed to be accurate but is not warranted to be whether originating with QR inc. or not. Recipients are advised to confirm in advance of need that the information is current, applicable, and suitable to their circumstances.

Recommendations for the use of this product are based on reliable tests. No guarantee of results are implied where conditions are beyond our control. Under no circumstances or conditions, either expressed or implied, will QR INC, be liable for damages in excess of the purchase price of this product.