


Section VII-Control Measures

Respiratory Protection(Specify Type)		
None needed under normal use condition.		
Ventillation	Local Exhaust	Special
	Mechanical(General)	Other
Protective Gloves		Eye Protection
None needed under normal use condition.		None needed.
Other Protective Clothing or Equipment		
None needed.		
Work/Hygiene Practices		
Minimize breathing vapor. Cleanse skin thoroughly after contact, before breaks and meals, and at the end of period.		

Page(4) Silicone oil

The information and recommendations contained herein, to the best of Ricoh's knowledge and belief, accurate and reliable as of the date issued. Ricoh does not warrant or guarantee their accuracy or reliability, and Ricoh shall not be liable for any loss or damage arising out of the use thereof.

The information and recommendations are offered for the user's responsibility to satisfy itself that they are suitable and complete for its particular use.



S. Shimizu

General Manager

P.L.P. Office, QC Division