MATERIAL SAFETY DATA SHEET



ENAMEL PRIMERS, CHROMATE PRIMER VARIPRIME®, CORLAR®

Эe	ÇU	OU	ı

Manufacturer
E. I. du Pont de Nemours & Co. (Inc.)
Automotive Products Department
Wilmington, Delaware 19898

Telephone: Product information (800) 441-7515 Medical emergency (800) 441-3637 Transportation emergency (800) 424-9300 (CHEMTREC)

Product: 215S, 329S, 615/616S, 824/825/826S, 1695S, 1696S, 1697S, LF 1697S, 3010S, 3011S, 3012S, 3055S, 1858S, 2085S

D.O.T. Hazard Class: Flammable Liquid Paint UN 1263

Hazardous Materials Identification System: H = 3, F = 3, R = 0.

Section II — Hazardous Ingredients (See Section X for ingredients listed by product code)

Ingredients	CAS No.	Vapor Pressure (20°C mm Hg.)	Exposure Limits*	
Denatured ethyl alcohol Butyl acetate	64-17-5 123-86-4	30 8	1000ppm-A,0 150ppm-A,0; 200ppm-A-(STEL)	
3. N-Butyl alcohol	71-36-3	5.5	100ppm-0; 25ppm-D;	
4. Acetone	67-64-1	184	50ppm-C-A 750ppm-A; 1000ppm-O; 1000ppm-A-(STEL)	
5. Methyl ethyl ketone	78-93-3	71	200ppm-A,0; 300ppm-A-(STEL)	
6. Methyl isobutyl ketone	108-10-1	15	50ppm-A; 150ppm-O; 75ppm-A-(STEL)	
7. Methyl isobutyl carbinol	108-11-2	2.2	25ppm-A,0; 40ppm-A-(STEL)	
8. Toluene	108-88-3	36.7	100ppm-A; 200ppm-A; 200ppm-O; 150ppm-A-(STEL); 300ppm-O-C; 500ppm-O Max 10 Min	
9. Isopropyl alcohol	67-63-0	33	400ppm-A,O; 500ppm-A-(STEL)	
10. Propylene glycol mono- methyl ether 11. Propylene glycol	107-98-2	10.9	100ppm-A	
monomethyl ether acetate 12. Xylene	108-65-6 1330-20-7	3.8 25	Unknown 100ppm-A,0; 150ppm-A-(STEL)	

13. Aromatic hydro-				
carbons	64742-95-6	10	25ppm-0; 50ppm-D	
14. Butyl benzyl phthalate	85-68-7	0.8	5 mg/m³-D	
15. VM&P naphtha	++ .	15	100ppm-D; 300ppm-A;	
16. Medium mineral			500ppm-0	
spirits	64742-88-7	10	100ppm-A,D; 500ppm-0	
17. Heavy naphtha 18. Phosphoric	64742-48-9	None	100ppm-D	
acid 19. Calcium	7664-38-2	None	2.0 mg/m³-A,0	
extender	None	None	10 mg/m³-A,D; 15 mg/m³-0	
20. Lead oxide	1317-36-8	None	150 μg/m³-A; 50 μg/m³-0,D	
21. Barium sulfate	7727-43-7	None	10 mg/m³-A	
22. Lead	7439-92-1	None	150 μg/m³-A, 50 μg/m³-O	
23. Epoxy type				
polymer 24. Crystalline	25068-38-6	None	Unknown	
silica 25. Hydrous	14808-60-7	None	0.1 mg/m³-A,0	
25. Hydrods magnesium				
silicate	14807-96-6	None	2.0 mg/m³-A-D; 5 mg/m³-0	
26. Titanium			· · · · · · · · ·	
dioxide	13463-67-7	None	10 mg/m³-A;	
27. Zinc chromate	13530-65-9	None	15 mg/m³-0	
ZI. ZIIIC CIIIOIIIale	13030-00-8	Molle	50 μg/m³-A, 100 μg/m³-O-Cr	
28. Zinc oxide	1314-13-2	None	10 mg/m ³ -A	
*A= ACGIH TLV, O = OSHA D = Du Pont Internal Limit,				

*A= ACGIH TLV, O = OSHA D = Du Pont Internal Limit, S = Supplier Furnished Limit, STEL = Short Term Exposure Limit (15 mins.), C = Ceiling

Section III - Physical Data

Evaporation rate: Slower than ether Gal. Wt. (#/gal): 6.8-13.4 Solubility in water: Miscible Vapor density: Heavier than air Bolling Range: 54°F-190°F Weight % volatile: 31.1-98.3% V.O.C. (#/gal): 3.5-8.0

Section IV — Fire & Explosion Data

Flash point (Closed Cup): 20-73°F Approx. flammable limits: 0.2-19.0 %

Extinguishing media: Water spray, foam, carbon dioxide, dry chemical

Special fire fighting procedures: Full protective equipment, including self-contained breathing apparatus, is recommended. Water from fog nozzles may be used to cool closed containers to prevent pressure build up.

Unusual fire & explosion hazards: When heated above the flash point, emits flammable vapors which, when mixed with air, can burn or be explosive. Fine mists or sprays may be flammable at temperatures below the flash point.

General effects

Ingestion: Gastro-intestinal distress.

In the unlikely event of ingestion, call a physician immediately

and have the names of ingredients available.

Inhalation: May cause nose and throat irritation. Repeated and prolonged overexposure to solvents may lead to permanent brain and nervous system damage. Eye watering, headaches, nausea, dizziness and loss of coordination are signs that solvent levels are too high.

If affected by inhalation of vapor or spray mist, remove to

If affected by inhalation of vapor or spray mist, remove to fresh air. If breathing difficulty persists, or occurs later, consult

a physician.

Skin or eye contact: May cause irritation or burning of the eyes.

Repeated or prolonged liquid contact may cause skin irritation with discomfort and dermatitis.

In case of eye contact, immediately flush with plenty of water

for at least 15 minutes; call a physician. In case of skin contact, wash with soap and water. If irritation

occurs, contact a physician.

Specific effects

Butyl Acetate: Extremely high concentrations have caused blood changes and weakness in laboratory animals. N-Butyl Alcohol: Liquid splashes in the eye may result in chemical burns. Methyl Ethyl Ketone: High concentrations have caused embryotoxic effects in laboratory animals. Methyl Ethyl Ketone (MEK) has been demonstrated to potentiate (i.e., shorten the time of onset) the peripheral neuropathy caused by either N-Hexane or Methyl N-Butyl Ketone. MEK by itself has not been demonstrated to cause peripheral neuropathy. Liquid splashes in the eye may result in chemical burns. Methyl Isobutyl Ketone: Recurrent overexposure may result in liver and kidney injury. Methyl Isobutyl Carbinol: Male rats exposed to very high airborne levels showed an increase in kidney weights. These effects were not seen in male rats exposed to lower concentrations, or in female rats at the same level. Liquid splashes in the eye may result in chemical burns. Extremely high concentrations have caused blood changes and weakness in laboratory animals. Toluene: Recurrent overexposure may result in liver and kidney injury. High airborne levels have produced irregular heart beats in animals and occasional palpitations in humans. Rats exposed to very high airborne levels have exhibited high frequency hearing deficits. The significance of this to man is unknown. Isopropyl Alcohol: Ingestion studies on laboratory animals showed that very high oral doses caused increased liver and kidney weights. High oral doses have caused anemia in laboratory animals. Propylene Glycol Monomethyl Ether: May cause temporary upper respiratory and/or lung irritation with cough, difficulty breathing, or shortness of breath. Can be absorbed through the skin in harmful amounts. Propylene Glycol Monomethyl Ether Acetate: May cause moderate eye burning. Recurrent overexposure may result in liver and kidney injury. Xylene: High concentrations have caused embryotoxic effects in laboratory animals. Recurrent overexposure may result in liver and kidney injury. Can be absorbed through the skin in harmful amounts. Butyl Benzyl Phthalate: Extremely high oral doses have caused tissue changes in the liver and testes of laboratory animals. Extremely high vapor aerosol doses have cause atrophy of the spleen and reproductive organs. Mice and rats were fed diets containing 0.6% and 1.2% butyl benzyl phthalate. At the highest dose, leukemias of the blood forming system were seen in female rats. No leukemia effect was seen in the female rats fed the lower level or in any of the mice. VM&P Naphtha, Medium Mineral Spirits and Heavy Naphtha: Laboratory studies with rats have shown that petroleum distillates cause kidney damage and kidney or liver tumors. These effects were not seen in similar studies with guinea pigs, dogs, or monkeys. Several studies evaluating petroleum workers have not shown significant

increases of kidney damage nor kidney or liver tumors. Phosphoric Acid: Prolonged skin contact may cause chemical burns. Liquid splashes in the eye may result in chemical burns. Lead Oxide and Lead: Overexposure to lead may cause adverse effects to the blood forming, nervous, urinary, reproductive systems including embryotoxic effects. Symptoms may include loss of appetite, anemia, disturbance of sleep and fatigue. See OSHA Lead Standard 29CFR1910.1025 for exposures longer than 8 hours. The OSHA exposure limit is reduced by this formula — limit (in μ g/m³) = 400/hours worked in the day. Lead can be absorbed through the skin in harmful amounts. Epoxy Type Polymer: Repeated exposure may cause allergic skin rash, itching, swelling. Has shown mutagenic activity in laboratory cell culture tests. Crystalline Silica: Repeated overexposure to crystalline silica may lead to typical X-ray changes and chronic lung disease. Hydrous Magnesium Silicate: Repeated and prolonged overexposure to talc may lead to typical X-ray changes and chronic lung disease. Titanium Dioxide: In a lifetime inhalation test, lung cancers were found in some rats exposed to 250 mg/m³ respirable titanium dust. Analysis of the titanium dioxide concentrations in the rat's lungs showed that the lung clearance mechanism was overwhelmed and that the results at the massive 250 mg/m3 level are not relevant to the workplace. Zinc Chromate: Health studies have shown that zinc chromate pigment manufacturing may be associated with an increased risk of lung cancer. Is an IARC, NTP or OSHA carcinogen.

Section VI — Reactivity Data

Stability: stable

Incompatibility (materials to avoid): none reasonably foreseeable Hazardous decomposition products: CO, CO₂, smoke, oxides of heavy metals reported in Section II

Hazardous polymerization: will not occur

Section VII - Spill or Leak Procedures

Steps to be taken in case material is released or spilled: Ventilate area. Remove sources of ignition. Prevent skin contact and breathing of vapor. Wear a properly fitted vapor/particulate respirator (NIOSH/MSHA TC-23C). Confine and remove with inert absorbant.

Waste disposal method: Do not allow material to contaminate ground water systems. Incinerate absorbed material in accordance with federal, state, and local requirements. Do not incinerate in closed containers.

Section VIII — Special Protection Information

Respiratory: Do not breathe vapors or mists.

Wear a properly fitted vapor/particulate respirator approved by NIOSH/MSHA (TC-23C) during application and until all vapors and spray mists are exhausted. In confined spaces or in situations where continuous spray operations are typical or if proper respirator fit is not possible, wear a positive pressure, supplied-air respirator (TC-19C). In all cases, follow the respirator manufacturer's directions for respirator use; do not permit anyone without protection in the painting area.

Ventilation: Provide sufficient ventilation in volume and pattern to keep contaminants below applicable OSHA requirements.

Protective clothing: Neoprene gloves and coveralls are recommended.

Eye protection: Desirable in all industrial situations. Include splash guards or side shields.

Section IX — Special Precautions

Precautions to be taken in handling and storing: Observe label precautions. Keep away from heat, sparks and flame. Close container after each use. Ground containers when pouring. Wash thoroughly after handling and before eating or smoking. Do not store above 120°F.

Other precautions: Do not sand, flame cut, braze or weld dry coating without a NIOSH/MSHA approved respirator or appropriate ventilation.

Section X — Hazardous Ingredients by Product Code			
Product Code	Ingredients (See Section II)		
2158	4, 5, 8, 12, 14, 25, 26, 27, 28		
329S	8, 13		
615S/616S	1, 2, 3, 4, 6, 8, 9, 11, 12, 15, 18, 21, 25, 26,		
	27, 28		
824S/826S	2, 3, 5, 7, 8, 9, 10, 11, 12, 13, 16, 19, 21, 23		
	25, 26		
825S/826S	3, 5, 7, 8, 9, 10, 12, 13, 16, 23, 24, 25, 27		
1695S	12, 13, 16, 17, 21, 22, 25, 26, 28		
1696S	12, 13, 16, 17, 21, 22, 25, 26, 28		
1697S	12, 13, 16, 17, 21, 22, 25, 28		
LF1697S	12, 13, 16, 17, 21, 25, 28		
1858S	3, 12, 13, 16, 17, 21, 22, 25, 26, 28		
2085\$	12, 13, 16, 17, 25, 27, 28		

Product Code	Ingredients (See Section II)
3010S	12, 13, 16, 20, 21, 22, 25, 26, 28
3011S	8, 9, 12, 13, 15, 16, 20, 21, 22, 25,
	26, 28
3012S	8, 9, 12, 13, 15, 16, 20, 21, 22, 25, 28
3055S	8, 9, 12, 13, 15, 16, 20, 21, 22, 25, 28

Notice: The data in this material safety data sheet relate only to the specific material designated herein and do not relate to use in combination with any other material or in any process.

"The following notice is required by California Proposition 65. 'Warning: This product contains chemicals known to the State of California to cause cancer, birth defects or other reproductive harm."

Product Manager Refinish Sales