# FISKE BROTHERS REFINING CO. DAVIS-HOWLAND OIL CO

## MATERIAL SAFETY DATA SHEET

200 ANDERGOAM VINUE

	. 630-AA-W, No. 630	-AAA SECTI		ENCY TELEPHONE NO
NUFACTURER'S NA Fiske Brothe:	rs Refining Company	·	419	0-691-2491
o <b>osess (Number, Si</b> 1500 Oakdale	reet, City, State, and ZIP Code Avenue, P.O. Box 8	) 3038 - Statior	"A", Toledo, Ohio	43605
HEMICAL NAME AND	O SYNONYMS		TRADE NAME AN	RIPLATE 630 Series
	roleum Hydrocarbons		FORMULA Lithium Soap, Minera	l Oil, and Additives
	SECTION	ON II HAZARD	OUS INGREDIENTS	
			zardous	% TL (Uni
ر در المساور ا المساور المساور المساو				
		SECTION III	PHYSICAL DATA	
IOILING POINT (F.)		> 550°F.	SPECIFIC GRAVITY (H20=1)	0.94-0
APOR PRESSURE (m	vn Hg.)	< 0.01 mm	PERCENT VOLATILE BY VOLUME (%)	Nil
VAPOR DENSITY IA	(J#=1)	<b>&gt;</b> 5	EVAPORATION RATE IN-Butyl Acetate = :	1)
SOLUBILITY IN WAT	EA	Insoluble		
appearance and	CDOR Smooth, tan g	rease with mi	neral oil odor	
	SECTION	ly fire and e	XPLOSION HAZARD DATA	ثان بالمجيدة والأن مرسوب الأباشات البريق المتحدد بيان بي المشابق بي المنابق والمراوي
FLASH POINT IME	COC - 400°F.		FLAMMABLE LIMITS	Lei Uei
EXTINGUISHING M	Foam, Dry Chem	nical, Carbon	Dioxide, or Water Sp	ray
	HTING PROCEDURES	-or lise air-s	upplied rescue equip	ment for enclosed area
SPECIAL FIRE FIGH	containers with wat	GI. ODC GII O		
SPECIAL FIRE FIGH	•		•	
Cool exposed	NO EXPLOSION HAZAROS	Do not sto	ore or mix with stron	g oxidants.
Cool exposed			ore or mix with stron	
Cool exposed			The second se	g oxidants. d, as they may explode
Cool exposed	NERS retain residue.	. Do not cut,	The second se	
Cool exposed	NERS retain residue.	. Do not cut,	drill, grind, or wel	
UNUSUAL FIRE AS	NERS retain residue.	Do not cut,	drill, grind, or wel	
UNUSUAL FIRE AFE	NERS retain residue.  UNSTABLE  STABLE	SECTION V RI CONGITION X	drill, grind, or wel	d, as they may explode

X

WILL NOT OCCUR

HAZARDOUS

POLYMERIZATION

### SECTION VI MEALTH HAZARU DATA

THE COURT OF LIGHT SCHOOL	- )				the state of the s							
THRESHOLD LIMIT VALUE	5mcr/m <sup>m</sup>	for	011	mict	in	air	OCHA	Regulation	29	CFR	1910	1000
	J:::(9/ III	イヘエ	OTT	111772	-1-11	وسلسلمكن	COTTU	1/G G a Ta CT OIL	2	CT 17	T > T > .	TOOL

The same

DATE PREPARED

Prolonged or repeated skin contact may cause skin irritation. Product contacting the eyes may cause eye irritation. Human health risks vary from person to person. As a precaution, exposure to liquids, vapors, mists and fumes should be minimized. This product has a low order of acute oral toxicity.

EMERGINCY AND FIRST AID PROCEDURES
EYE CONTACT: Flush with clear water for 15 minutes or until irritation subsides. If irritation persists, consult a physician. SKIN CONTACT: Remove any contaminated clothing and wash thoroughly with soap and warm water. If injected under skin, regardless of the appearance or its size, contact a physician IMMEDIATELY. Delay may cause loss of affected part of the body. INHALATION: Vapor pressure is very low and inhalation at room temperature is not a problem. If overcome by vapor from hot product, immediately remove from exposure and call a physician. If over exposed to oil mist, remove from further exposure until excessive oil mist condition subsides. INGESTION: If ingested, call a physician immediately.

#### SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR STILLED
Scrape up grease, wash remainder with suitable petroleum solvent or add absorbent. Keep petroleum products out of sewers and water courses. Advise authorities if product has entered or may enter sewers and water courses.

WASTE CISPOSAL WETHOO
Assure conformity with applicable disposal regulations. Dispose of absorbed material at an approved waste disposal facility or site.

#### SECTION VIII SPECIAL PROTECTION INFORMATION RESPIRATORY PROTECTION (Specify 1794) Normally not needed SPICIAL LOCAL EXHAUST VENTILATION Use to capture fumes and vapors MECHANICAL (General) M3HTO EYE MOTECTION WGTECTIVE GLOVES Use oil-resistant gloves, if needed If chance of eye contact, wear goggles. OTHER MOTECTIVE EQUIPMENT Use oil-resistant apron, if needed,

#### SECTION IX SPECIAL PRECAUTIONS

recautions to it taken in manouing and storing
Keep containers closed when not in use. Do not handle or store near heat, sparks, flame or strong oxidants.

Avoid breathing oil mist. Remove oil-soaked clothing and launder before reuse. Cleanse skin thoroughly after contact.

November, 1985

PREPARED BY:

mem Kuhlman, Technical Advisor