

SECTION I

SECTION II — INGREDIENTS

☐ SECTION III — PHYSICAL DATA

☐ SECTION IV-FIRE AND EXPLOSION HAZARD DATA

SECTION IV-FIRE AND EXPLOSION HAZARD DATA			
FLASH POINT (method used)		None - boils at 212°F	FLAMMABLE LIMITS
EXTINGUISHING MEDIA		Carbon dioxide (CO ₂), water flood, dry chemical, foam	N/A
SPECIAL FIRE FIGHTING PROCEDURES		Use water to cool fire exposed containers. If a leak or spill has not ignited, use water spray to disperse the vapors and to provide protection for persons attempting to stop	
UNUSUAL FIRE AND EXPLOSION HAZARDS		None	

☐ SECTION V-HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE		May cause eye and skin irritation.	THRESHOLD LIMIT VALUE (OF MIXTURE) Not established by ACGIH; recommend using 5 mg./cu. meter limit as for mineral oil mists.
EMERGENCY AND FIRST AID PROCEDURES			
Eyes. Flush with water for fifteen minutes. Call a physician. Skin. Wash exposed areas with soap and water. Ingestion. If concentrate is swallowed, do not induce vomiting. drink water or milk and call a physician.			

☐ SECTION VI-REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
COMPATIBILITY (materials to avoid) Mineral acids, petroleum oil			
HAZARDOUS DECOMPOSITION PRODUCTS Ammonia, CO ₂ , and CO by thermal decomposition			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

☐ SECTION VII-SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED		Contain spill. Remove to drum with pump or inert sorbent such as clay. Avoid contaminating sewers and waterways. Avoid contact with incompatible materials.
WASTE DISPOSAL METHOD		Dispose of in accordance with Federal, State and local regulations.

☐ SECTION VIII-SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type) Protection required over 5 mg./cu. meter mist ?		
VENTILATION	LOCAL EXHAUST (Specify Rate) Maintain adequate ventilation	SPECIAL
	MECHANICAL (General) (Specify Rate)	OTHER
PROTECTIVE GLOVES Rubber Gloves when handling concentrate		EYE PROTECTION Splash goggles, when handling concentrate
OTHER PROTECTIVE EQUIPMENT Impervious apron		

☐ SECTION IX-SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING		Wash thoroughly after handling. Wash contaminated clothing.
Avoid contact with skin and eyes.		
OTHER PRECAUTIONS		Contact with mist may cause irritation of eyes.

Signature (print)
Signature
Asst. Technical Director
August 19, 1986