

SYRACUSE CITY SCHOOL DISTRICT

LEMOYNE ELEMENTARY SCHOOL

SAMPLE DATE: 09/17/2016 ANALYSIS DATE: 11/09/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 005 - Classroom	Sink	Public Access	LM-014	LM-S101	2.9	None
Rm. 005 - Classroom	Fountain	Public Access	LM-001	LM-F101	< 1.0	None
Rm. 005C - Classroom Bathroom	Sink	Public Access	LM-015	LM-S102	2.3	None
Rm. 100E - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	LM-028	LM-S115	5.8	None
Rm. 100F - Kitchen Serving Room	Sink	Secured - SCSD Staff Only	LM-029	LM-S116	1.7	None
Rm. 100F - Kitchen Serving Room	Sink	Secured - SCSD Staff Only	LM-030	LM-S117	1.5	None
Rm. 100F - Kitchen Serving Room	Sink	Secured - SCSD Staff Only	LM-031	LM-S118	1.8	None
Rm. 100F - Kitchen Serving Room	Sink	Secured - SCSD Staff Only	LM-032	LM-S119	2.9	None
Rm. 101 - Classroom	Sink	Public Access	LM-026	LM-S113	< 1.0	None
Rm. 101 - Classroom	Fountain	Public Access	LM-005	LM-F105	< 1.0	None
Rm. 101A - Classroom Bathroom	Sink	Public Access	LM-027	LM-S114	5.1	None
Rm. 101B - Hallway/Corridor	Fountain	Public Access	LM-002	LM-F102	< 1.0	None
Rm. 101J - Hallway/Corridor	Fountain	Public Access	LM-006	LM-F106	< 1.0	None
Rm. 101J - Hallway/Corridor	Fountain	Public Access	LM-007	LM-F107	< 1.0	None
Rm. 102A - Classroom Bathroom	Sink	Public Access	LM-023	LM-S110	6.8	None
Rm. 103 - Classroom	Sink	Public Access	LM-025	LM-S112	2.3	None
Rm. 103 - Classroom	Fountain	Public Access	LM-004	LM-F104	1.6	None
Rm. 103A - Classroom Bathroom	Sink	Public Access	LM-024	LM-S111	< 1.0	None
Rm. 104 - Classroom Bathroom	Sink	Public Access	LM-022	LM-S109	1.2	None
Rm. 105 - Classroom	Sink	Public Access	LM-021	LM-S108	< 1.0	None
Rm. 105 - Classroom	Fountain	Public Access	LM-003	LM-F103	1.1	None
Rm. 105A - Classroom Bathroom	Sink	Public Access	LM-020	LM-S107	5.1	None
Rm. 106B - Storage Room	Sink	Secured - SCSD Staff Only	LM-016	LM-S103	1.1	None
Rm. 110A - Clinic Room	Sink	Public Access	LM-037	LM-S124	2.5	None
Rm. 110B - Nurse's Bathroom	Sink	Public Access	LM-038	LM-S125	2.7	None
Rm. 113 - Classroom	Sink	Public Access	LM-043	LM-S130	1.3	None
Rm. 113 - Classroom	Fountain	Public Access	LM-008	LM-F108	1.4	None
Rm. 113A - Classroom Bathroom	Sink	Public Access	LM-042	LM-S129	< 1.0	None
Rm. 115 - Classroom	Sink	Public Access	LM-045	LM-S132	< 1.0	None

SYRACUSE CITY SCHOOL DISTRICT

LEMOYNE ELEMENTARY SCHOOL

SAMPLE DATE: 09/17/2016 ANALYSIS DATE: 11/09/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 115 - Classroom	Fountain	Public Access	LM-009	LM-F109	1.6	None
Rm. 115A - Classroom Bathroom	Sink	Public Access	LM-044	LM-S131	7.0	None
Rm. 118 - Classroom	Sink	Public Access	LM-046	LM-S133	< 1.0	None
Rm. 118 - Classroom	Fountain	Public Access	LM-010	LM-F110	2.3	None
Rm. 118A - Classroom Bathroom	Sink	Public Access	LM-047	LM-S134	2.2	None
Rm. 121A - Storage Room	Sink	Secured - SCSD Staff Only	LM-039	LM-S126	4.7	None
Rm. 121A - Storage Room	Sink	Secured - SCSD Staff Only	LM-041	LM-S128	< 1.0	None
Rm. 121E - Office Bathroom	Sink	Secured - SCSD Staff Only	LM-040	LM-S127	1.8	None
Rm. 134 - Boy's Bathroom	Sink	Public Access	LM-033	LM-S120	3.3	None
Rm. 134 - Boy's Bathroom	Sink	Public Access	LM-034	LM-S121	5.6	None
Rm. 134A - Girl's Bathroom	Sink	Public Access	LM-035	LM-S122	6.1	None
Rm. 134A - Girl's Bathroom	Sink	Public Access	LM-036	LM-S123	1.4	None
Rm. 138 - Gym Bathroom	Sink	Public Access	LM-017	LM-S104	< 1.0	None
Rm. 141 - Girl's Bathroom	Sink	Public Access	LM-019	LM-S106	4.8	None
Rm. 141A - Boy's Bathroom	Sink	Public Access	LM-018	LM-S105	3.5	None
Rm. 201F - Hallway/Corridor	Fountain	Public Access	LM-011	LM-F111	< 1.0	None
Rm. 201F - Hallway/Corridor	Fountain	Public Access	LM-012	LM-F112	< 1.0	None
Rm. 204 - Lounge	Sink	Secured - SCSD Staff Only	LM-059	LM-S146	< 1.0	None
Rm. 204A - Lounge Bathroom	Sink	Secured - SCSD Staff Only	LM-061	LM-S148	< 1.0	None
Rm. 204B - Lounge Bathroom	Sink	Secured - SCSD Staff Only	LM-060	LM-S147	1.4	None
Rm. 206 - Classroom	Sink	Public Access	LM-053	LM-S140	1.8	None
Rm. 206 - Classroom	Sink	Public Access	LM-054	LM-S141	3.2	None
Rm. 212A - Girl's Bathroom/Corridor	Sink	Public Access	LM-049	LM-S136	1.1	None
Rm. 212A - Girl's Bathroom/Corridor	Sink	Public Access	LM-050	LM-S137	3.0	None
Rm. 212B - Boy's Bathroom Sink/Corridor	Sink	Public Access	LM-051	LM-S138	15.0	SCSD to replace fixture
Rm. 212B - Boy's Bathroom Sink/Corridor	Sink	Public Access	LM-052	LM-S139	16.0	SCSD to replace fixture
Rm. 212D - Staff Bathroom	Sink	Secured - SCSD Staff Only	LM-055	LM-S142	1.1	None
Rm. 219A - Library Office	Sink	Secured - SCSD Staff Only	LM-048	LM-S135	< 1.0	None
Rm. 222 - Hallway/Vestibule	Sink	Public Access	LM-056	LM-S143	< 1.0	None

SYRACUSE CITY SCHOOL DISTRICT

LEMOYNE ELEMENTARY SCHOOL

SAMPLE DATE: 09/17/2016 ANALYSIS DATE: 11/09/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 222 - Hallway/Vestibule	Sink	Public Access	LM-057	LM-S144	3.7	None
Rm. 222 - Hallway/Vestibule	Fountain	Public Access	LM-013	LM-F113	< 1.0	None
Rm. 222 - Hallway/Vestibule	Sink	Public Access	LM-058	LM-S145	8.3	None

Notes:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-004
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1615976
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.