

SYRACUSE CITY SCHOOL DISTRICT
HUNTINGTON PK- GRADE 8 SCHOOL

SAMPLE DATE: 09/25/2016 ANALYSIS DATE: 11/17/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. A103 - Hallway/Vestibule	Fountain	Public Access	SCSD-HN-073	HN-F200	< 1.0	None
Rm. A104 - Girl's Bathroom	Sink	Public Access	SCSD-HN-007	HN-S207	2.9	None
Rm. A104 - Girl's Bathroom	Sink	Public Access	SCSD-HN-008	HN-S208	2.1	None
Rm. A104 - Girl's Locker Room Bathroom	Sink	Public Access	SCSD-HN-018	HN-S218	2.2	None
Rm. A105 - Boy's Bathroom	Sink	Public Access	SCSD-HN-009	HN-S209	2.0	None
Rm. A105 - Boy's Bathroom	Sink	Public Access	SCSD-HN-010	HN-S210	5.5	None
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	SCSD-HN-001	HN-S201	< 1.0	None
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	SCSD-HN-002	HN-S202	< 1.0	None
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	SCSD-HN-003	HN-S203	1.4	None
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	SCSD-HN-004	HN-S204	1.2	None
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	SCSD-HN-005	HN-S205	2.1	None
Rm. A117A - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-006	HN-S206	1.9	None
Rm. A132A - Boy's Coach Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-015	HN-S215	49.0	SCSD replaced fixture
Rm. A135 - Boy's Locker Room Bathroom	Sink	Public Access	SCSD-HN-014	HN-S214	1.4	None
Rm. A137 - Teacher's Resource Room	Sink	Secured - SCSD Staff Only	SCSD-HN-011	HN-S211	< 1.0	None
Rm. A137A - Teacher's Resource Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-012	HN-S212	2.2	None
Rm. A137A - Teacher's Resource Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-013	HN-S213	< 1.0	None
Rm. A139 - Gym	Fountain	Public Access	SCSD-HN-074	HN-F201	< 1.0	None
Rm. A139 - Gym	Fountain	Public Access	SCSD-HN-075	HN-F202	< 1.0	None
Rm. A146 - Girl's Coach Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-016	HN-S216	4.0	None
Rm. A149 - Girl's Locker Room Bathroom	Sink	Public Access	SCSD-HN-017	HN-S217	< 1.0	None
Rm. A158 - Boy's Locker Room Bathroom	Sink	Public Access	SCSD-HN-019	HN-S219	< 1.0	None
Rm. A162A - Office Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-020	HN-S220	1.3	None
Rm. A201 - Hallway/Corridor	Fountain	Public Access	SCSD-HN-078	HN-F206	< 1.0	None
Rm. A211 - Hallway/Vestibule	Sink	Public Access	SCSD-HN-024	HN-S224	1.1	None
Rm. A211 - Hallway/Vestibule	Sink	Public Access	SCSD-HN-025	HN-S225	1.1	None
Rm. A211 - Hallway/Vestibule	Sink	Public Access	SCSD-HN-026	HN-S226	1.1	None
Rm. A211 - Hallway/Vestibule	Sink	Public Access	SCSD-HN-027	HN-S227	70.0	SCSD replaced fixture
Rm. A240 - Classroom	Sink	Public Access	SCSD-HN-023	HN-S223	< 1.0	None

SYRACUSE CITY SCHOOL DISTRICT
HUNTINGTON PK- GRADE 8 SCHOOL

SAMPLE DATE: 09/25/2016 ANALYSIS DATE: 11/17/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. B01 - Technology Room	Sink	Public Access	SCSD-HN-033	HN-S100	3.4	None
Rm. B01 - Technology Room	Sink	Public Access	SCSD-HN-034	HN-S101	4.0	None
Rm. B06 - Music Room	Sink	Public Access	SCSD-HN-040	HN-S107	3.3	None
Rm. B08A - Water Service Room	Hose Bib at Meter Assembly	Secured - SCSD Staff Only	SCSD-HN-032	HN-M100	45.0	SCSD affixed warning sign at fixture
Rm. B20 - Hallway/Corridor	Fountain	Public Access	SCSD-HN-080	HN-F100	1.4	None
Rm. B20A - Boy's Bathroom	Sink	Public Access	SCSD-HN-035	HN-S102A	8.6	None
Rm. B20A - Boy's Bathroom	Sink	Public Access	SCSD-HN-036	HN-S102B	6.2	None
Rm. B20G - Girl's Bathroom	Sink	Public Access	SCSD-HN-037	HN-S104	6.5	None
Rm. B20G - Girl's Bathroom	Sink	Public Access	SCSD-HN-038	HN-S105	6.0	None
Rm. B20G - Girl's Bathroom	Sink	Public Access	SCSD-HN-039	HN-S106	3.2	None
Rm. B104 - Classroom	Sink	Public Access	SCSD-HN-051	HN-S119	< 1.0	None
Rm. B104A - Classroom Bathroom	Sink	Public Access	--	HN-S118	--	Fixture out-of-service
Rm. B106 - Classroom	Sink	Public Access	SCSD-HN-053	HN-S121	< 1.0	None
Rm. B106A - Classroom Bathroom	Sink	Public Access	SCSD-HN-052	HN-S120	2.0	None
Rm. B108 - Classroom	Sink	Public Access	SCSD-HN-059	HN-S127	1.7	None
Rm. B115 - Classroom	Sink	Public Access	SCSD-HN-041	HN-S108	2.9	None
Rm. B119A - Hallway/Corridor	Fountain	Public Access	SCSD-HN-081	HN-F101	1.3	None
Rm. B119A - Hallway/Corridor	Fountain	Public Access	SCSD-HN-082	HN-F102	2.6	None
Rm. B119L - Hallway/Corridor	Fountain	Public Access	--	HN-F204	--	Fixture out-of-service
Rm. B119L - Hallway/Corridor	Fountain	Public Access	SCSD-HN-077	HN-F205	4.0	None
Rm. B122 - Boy's Bathroom	Sink	Public Access	SCSD-HN-057	HN-S125	< 1.0	None
Rm. B122 - Boy's Bathroom	Sink	Public Access	SCSD-HN-058	HN-S126	< 1.0	None
Rm. B124 - Girl's Bathroom	Sink	Public Access	SCSD-HN-054	HN-S122	21.0	SCSD replaced fixture
Rm. B124 - Girl's Bathroom	Sink	Public Access	SCSD-HN-055	HN-S123	6.1	None
Rm. B124 - Girl's Bathroom	Sink	Public Access	SCSD-HN-056	HN-S124	< 1.0	None
Rm. B129 - Staff Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-021	HN-S221	4.2	None
Rm. B136 - Girl's Bathroom	Sink	Public Access	SCSD-HN-046	HN-S113	1.5	None
Rm. B136 - Girl's Bathroom	Sink	Public Access	SCSD-HN-047	HN-S114	< 1.0	None
Rm. B137 - Boy's Bathroom	Sink	Public Access	SCSD-HN-044	HN-S111	< 1.0	None

SYRACUSE CITY SCHOOL DISTRICT
HUNTINGTON PK- GRADE 8 SCHOOL

SAMPLE DATE: 09/25/2016 ANALYSIS DATE: 11/17/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. B137 - Boy's Bathroom	Sink	Public Access	SCSD-HN-045	HN-S112	1.5	None
Rm. B140C - Office/Staff Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-050	HN-S117	< 1.0	None
Rm. B140D - Office/Staff Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-049	HN-S116	1.0	None
Rm. B140E - Mail Room	Sink	Secured - SCSD Staff Only	SCSD-HN-048	HN-S115	< 1.0	None
Rm. B142 - Nurse's Room	Sink	Public Access	SCSD-HN-043	HN-S110	1.3	None
Rm. B142C - Nurse's Bathroom	Sink	Public Access	SCSD-HN-042	HN-S109	1.6	None
Rm. B206 - Home & Careers Room	Sink	Public Access	SCSD-HN-060	HN-S128	1.6	None
Rm. B206 - Home & Careers Room	Sink	Public Access	SCSD-HN-061	HN-S129A	< 1.0	None
Rm. B207 - Classroom	Sink	Public Access	SCSD-HN-062	HN-S129B	< 1.0	None
Rm. B216 - Laboratory Room	Sink	Public Access	SCSD-HN-069	HN-S136	36.0	SCSD removed fixture from service
Rm. B216 - Laboratory Room	Sink	Public Access	--	HN-S137	--	Fixture out-of-service
Rm. B216 - Laboratory Room	Sink	Public Access	SCSD-HN-070	HN-S138	2.5	None
Rm. B216 - Laboratory Room	Sink	Public Access	--	HN-S139	--	Fixture out-of-service
Rm. B218 - Boy's Bathroom	Sink	Public Access	SCSD-HN-063	HN-S130	< 1.0	None
Rm. B218 - Boy's Bathroom	Sink	Public Access	SCSD-HN-064	HN-S131	< 1.0	None
Rm. B218 - Art Room	Sink	Public Access	SCSD-HN-071	HN-S140	2.5	None
Rm. B218 - Art Room	Sink	Public Access	SCSD-HN-072	HN-S141	1.2	None
Rm. B221 - Girl's Bathroom	Sink	Public Access	SCSD-HN-065	HN-S132	14.0	None
Rm. B221 - Girl's Bathroom	Sink	Public Access	SCSD-HN-066	HN-S133	9.3	None
Rm. B221 - Girl's Bathroom	Sink	Public Access	SCSD-HN-067	HN-S134	3.0	None
Rm. B223 - Staff Bathroom	Sink	Secured - SCSD Staff Only	SCSD-HN-022	HN-S222	< 1.0	None
Rm. B226 - Girl's Bathroom	Sink	Public Access	SCSD-HN-028	HN-S228	< 1.0	None
Rm. B226 - Girl's Bathroom	Sink	Public Access	SCSD-HN-029	HN-S229	1.1	None
Rm. B227 - Boy's Bathroom	Sink	Public Access	SCSD-HN-030	HN-S230	2.3	None
Rm. B227 - Boy's Bathroom	Sink	Public Access	SCSD-HN-031	HN-S231	2.3	None
Rm. B229D - Library Office Room	Sink	Secured - SCSD Staff Only	SCSD-HN-068	HN-S135	1.9	None
Rm. B236 - Hallway/Corridor	Fountain	Public Access	SCSD-HN-079	HN-F207	< 1.0	None
Rm. B236 - Hallway/Corridor	Fountain	Public Access	SCSD-HN-083	HN-F103	< 1.0	None
Rm. N104 - Pool	Fountain	Public Access	SCSD-HN-076	HN-F203	3.1	None

SYRACUSE CITY SCHOOL DISTRICT
HUNTINGTON PK- GRADE 8 SCHOOL

SAMPLE DATE: 09/25/2016 ANALYSIS DATE: 11/17/2016

Notes:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-008
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1618445
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.