

SYRACUSE CITY SCHOOL DISTRICT

FRAZER PK-GRADE 8 SCHOOL

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 11/22/2016 and 11/27/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 000 - Hallway/Vestibule	Fountain	Public Access	--	FR-F104	--	Fixture not operating
Rm. 000 - Hallway/Vestibule	Fountain	Public Access	FR-022	FR-F105	< 1.0	None
Rm. 000A - Hallway Corridor	Fountain	Public Access	FR-002	FR-F100	1.1	None
Rm. 000A - Hallway Corridor	Fountain	Public Access	FR-003	FR-F101	< 1.0	None
Rm. 0T1A - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-005	FR-S101	8.3	None
Rm. 0T1B - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-004	FR-S100	3.2	None
Rm. 002B - Gym Office Bathroom	Sink	Secured - SCSD Staff Only	FR-024	FR-S118	4.2	None
Rm. 002C - Girl's Locker Room	Sink	Public Access	FR-025	FR-S119	2.2	None
Rm. 002C - Girl's Locker Room	Sink	Public Access	FR-026	FR-S120	5.0	None
Rm. 002C - Girl's Locker Room	Sink	Public Access	FR-027	FR-S121	4.3	None
Rm. 003B - Gym Office Bathroom	Sink	Secured - SCSD Staff Only	FR-023	FR-S117	5.4	None
Rm. 003C - Boy's Locker Room	Sink	Public Access	FR-019	FR-S114	2.7	None
Rm. 003C - Boy's Locker Room	Sink	Public Access	FR-020	FR-S115	2.1	None
Rm. 003C - Boy's Locker Room	Sink	Public Access	FR-021	FR-S116	14.0	None
Rm. 05B - Technology Room	Sink	Public Access	FR-015	FR-S110	5.8	None
Rm. 007 - Lounge	Sink	Secured - SCSD Staff Only	FR-016	FR-S111	< 1.0	None
Rm. 007A - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-017	FR-S112	2.4	None
Rm. 007B - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-018	FR-S113	< 1.0	None
Rm. 008A - Cafeteria	Fountain	Public Access	FR-006	FR-F102	3.9	None
Rm. 008A - Cafeteria	Fountain	Public Access	-	FR-F103	-	Fixture not operating
Rm. 008E - Kitchen	Sink	Secured - SCSD Staff Only	FR-007	FR-S102	< 1.0	None
Rm. 008E - Kitchen	Sink	Secured - SCSD Staff Only	FR-008	FR-S103	< 1.0	None
Rm. 008E - Kitchen	Sink	Secured - SCSD Staff Only	FR-009	FR-S104	1.7	None
Rm. 008E - Kitchen	Sink	Secured - SCSD Staff Only	FR-010	FR-S105	2.4	None
Rm. 008E - Kitchen	Sink	Secured - SCSD Staff Only	FR-011	FR-S106	1.8	None
Rm. 008J - Kitchen Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-012	FR-S107	1.2	None
Rm. 008K - Custodian's Bathroom	Sink	Secured - SCSD Staff Only	FR-013	FR-S108	2.6	None
Rm. 009 - Technology Room	Sink	Public Access	FR-014	FR-S109	3.3	None
Rm. 014 - Mechanical/Meter Room	Hose Bib at Meter Assembly	Secured - SCSD Staff Only	FR-001	FR-M100	35.0	SCSD to affix warning sign

SYRACUSE CITY SCHOOL DISTRICT

FRAZER PK-GRADE 8 SCHOOL

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 11/22/2016 and 11/27/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 1T1 - Hallway/Vestibule	Sink	Public Access	FR-056	FR-S141	< 1.0	None
Rm. 1T1 - Hallway/Vestibule	Sink	Public Access	FR-057	FR-S142	< 1.0	None
Rm. 1T1 - Hallway/Vestibule	Sink	Public Access	FR-058	FR-S143	5.9	None
Rm. 1T2 - Hallway/Vestibule	Sink	Public Access	FR-044	FR-S134	2.3	None
Rm. 1T2 - Hallway/Vestibule	Sink	Public Access	FR-045	FR-S135	11.0	None
Rm. 1T2 - Hallway/Vestibule	Sink	Public Access	FR-046	FR-S136	< 1.0	None
Rm. 100B - Hallway/Corridor	Fountain	Public Access	FR-053	FR-F113	< 1.0	None
Rm. 100B - Hallway/Corridor	Fountain	Public Access	FR-054	FR-F114	< 1.0	None
Rm. 100B - Hallway/Corridor	Fountain	Public Access	FR-055	FR-F115	< 1.0	None
Rm. 100H - Hallway/Corridor	Fountain	Public Access	FR-047	FR-F111	< 1.0	None
Rm. 101 - Classroom	Sink	Public Access	FR-038	FR-S130	< 1.0	None
Rm. 101 - Classroom	Fountain	Public Access	FR-039	FR-F109	3.1	None
Rm. 101A - Classroom	Sink	Public Access	FR-037	FR-S129	59.0	SCSD to replace fixture
Rm. 101J - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-040	FR-S131	2.5	None
Rm. 101K - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-041	FR-S132	< 1.0	None
Rm. 102A - Nurse's Bathroom	Sink	Public Access	FR-035	FR-S127	3.1	None
Rm. 102B - Exam Room	Sink	Public Access	FR-036	FR-S128	5.8	None
Rm. 105 - Special Education Room	Sink	Public Access	FR-034	FR-S126	< 1.0	None
Rm. 106 - Classroom	Sink	Public Access	FR-032	FR-S125	< 1.0	None
Rm. 106 - Classroom	Fountain	Public Access	FR-033	FR-F108	2.0	None
Rm. 106A - Classroom Bathroom	Sink	Public Access	FR-031	FR-S124	13.0	None
Rm. 107 - Classroom	Sink	Public Access	FR-029	FR-S123	23.0	SCSD to replace fixture
Rm. 107 - Classroom	Fountain	Public Access	FR-030	FR-F107	3.5	None
Rm. 107A - Classroom Bathroom	Sink	Public Access	FR-028	FR-S122	6.0	None
Rm. 116 - Resource Room	Sink	Public Access	FR-062	FR-S147	< 1.0	None
Rm. 117C - Work Room	Sink	Secured - SCSD Staff Only	FR-061	FR-S146	< 1.0	None
Rm. 118 - Work Room	Sink	Secured - SCSD Staff Only	FR-060	FR-S145	< 1.0	None
Rm. 118A - Work Room Bathroom	Sink	Secured - SCSD Staff Only	FR-059	FR-S144	2.8	None
Rm. 130 - Classroom	Sink	Public Access	FR-051	FR-S139	1.6	None

SYRACUSE CITY SCHOOL DISTRICT

FRAZER PK-GRADE 8 SCHOOL

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 11/22/2016 and 11/27/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 131A - Class Bathroom	Sink	Public Access	FR-052	FR-S140	3.8	None
Rm. 131A - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-049	FR-S138	3.0	None
Rm. 131B - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-048	FR-S137	3.2	None
Rm. 134B - Classroom Bathroom	Sink	Public Access	FR-042	FR-S133	4.2	None
Rm. 142 - Classroom	Fountain	Public Access	FR-043	FR-F110	< 1.0	None
Rm. L-10 - Hallway/Corridor	Fountain	Public Access	FR-050	FR-F112	< 1.0	None
Rm. 200 - Computer Lab	Sink	Public Access	FR-073	FR-S158	< 1.0	None
Rm. 200A - Hallway/Corridor	Fountain	Public Access	FR-084	FR-F120	< 1.0	None
Rm. 200A - Hallway/Corridor	Fountain	Public Access	FR-085	FR-F121	< 1.0	None
Rm. 200A - Dark Room	Sink	Public Access	FR-072	FR-S157	830.0	SCSD to remove fixture from service
Rm. 200A - Hallway/Corridor	Fountain	Public Access	--	FR-F119	--	Fixture not operating
Rm. 200D - Hallway/Corridor	Fountain	Public Access	--	FR-F118	--	Fixture not operating
Rm. 200H - Hallway/Corridor	Fountain	Public Access	--	FR-F116	--	Fixture not operating
Rm. 200H - Hallway/Corridor	Fountain	Public Access	FR-077	FR-F117	< 1.0	None
Rm. 203A - Work Room Bathroom	Sink	Secured - SCSD Staff Only	FR-070	FR-S155	1.6	None
Rm. 211 - Work Room	Sink	Secured - SCSD Staff Only	FR-069	FR-S154	4.6	None
Rm. 214 - Laboratory Room	Sink	Public Access	FR-065	FR-S150	2.4	None
Rm. 214 - Laboratory Room	Sink	Public Access	FR-066	FR-S151	3.0	None
Rm. 214 - Laboratory Room	Sink	Public Access	FR-067	FR-S152	< 1.0	None
Rm. 214 - Laboratory Room	Sink	Public Access	FR-068	FR-S153	1.2	None
Rm. 217 - Home & Careers Room	Sink	Public Access	FR-063	FR-S148	< 1.0	None
Rm. 217 - Home & Careers Room	Sink	Public Access	FR-064	FR-S149	< 1.0	None
Rm. 230 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-079	FR-S163	4.3	None
Rm. 231 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	FR-078	FR-S162	3.9	None
Rm. 231 - Classroom Bathroom	Sink	Public Access	FR-080	FR-S164	2.6	None
Rm. 249 - Art Room	Sink	Public Access	FR-071	FR-S156	1.1	None
Rm. 2T1 - Hallway/Vestibule	Sink	Public Access	FR-081	FR-S165	4.3	None
Rm. 2T1 - Hallway/Vestibule	Sink	Public Access	FR-082	FR-S166	< 1.0	None
Rm. 2T1 - Hallway/Vestibule	Sink	Public Access	FR-083	FR-S167	23.0	SCSD to replace fixture

SYRACUSE CITY SCHOOL DISTRICT

FRAZER PK-GRADE 8 SCHOOL

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 11/22/2016 and 11/27/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 2T2 - Hallway/Vestibule	Sink	Public Access	FR-074	FR-S159	3.9	None
Rm. 2T2 - Hallway/Vestibule	Sink	Public Access	FR-075	FR-S160	< 1.0	None
Rm. 2T2 - Hallway/Vestibule	Sink	Public Access	FR-076	FR-S161	4.7	None

Notes:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-013
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1619253
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.