

SYRACUSE CITY SCHOOL DISTRICT
SEYMOUR DUAL LANGUAGE ACADEMY SCHOOL PK-GRADE 5

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 12/02/2016, 12/03/2016 and 12/04/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 007 Boiler Room	Hose Bib at Meter Assembly	Secured - SCSD Staff Only	SR-001	SR-S200	10.0	None
Rm. 109 - Classroom	Sink	Public Access	SR-035	SR-S317	< 1.0	None
Rm. 114 - Classroom	Sink	Public Access	SR-047	SR-S329	< 1.0	None
Rm. 114 - Classroom	Fountain	Public Access	SR-056	SR-F304	< 1.0	None
Rm. 114A - Classroom Bathroom	Sink	Public Access	SR-046	SR-S328	< 1.0	None
Rm. 115 - Classroom	Sink	Public Access	SR-018	SR-S217	< 1.0	None
Rm. 115 - Classroom	Fountain	Public Access	SR-052	SR-F204	< 1.0	None
Rm. 115B - Classroom Bathroom	Sink	Public Access	SR-017	SR-S216	< 1.0	None
Rm. 116 - Classroom	Sink	Public Access	SR-016	SR-S215	< 1.0	None
Rm. 116 - Classroom	Fountain	Public Access	SR-051	SR-F203	< 1.0	None
Rm. 116B - Classroom Bathroom	Sink	Public Access	SR-015	SR-S214	< 1.0	None
Rm. 117 - Classroom	Sink	Public Access	SR-009	SR-S208	< 1.0	None
Rm. 117 - Classroom	Fountain	Public Access	SR-050	SR-F202	< 1.0	None
Rm. 117A - Classroom Bathroom	Sink	Public Access	SR-008	SR-S207	< 1.0	None
Rm. 118A - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	SR-010	SR-S209	< 1.0	None
Rm. 119 - Classroom	Sink	Public Access	SR-005	SR-S204	< 1.0	None
Rm. 119 - Classroom	Fountain	Public Access	SR-049	SR-F201	< 1.0	None
Rm. 123 - Hallway/Corridor	Fountain	Public Access	SR-048	SR-F200	< 1.0	None
Rm. 129 - Classroom Bathroom	Sink	Public Access	SR-006	SR-S205	< 1.0	None
Rm. 133 - Gym Staff Bathroom	Sink	Secured - SCSD Staff Only	SR-007	SR-S206	< 1.0	None
Rm. 142 - Girl's Bathroom	Sink	Public Access	SR-003	SR-S202	< 1.0	None
Rm. 142 - Girl's Bathroom	Sink	Public Access	SR-004	SR-S203	2.2	None
Rm. 143 - Boy's Bathroom	Sink	Public Access	SR-002	SR-S201	< 1.0	None
Rm. 156 - Hallway/Corridor	Fountain	Public Access	SR-055	SR-F303	< 1.0	None
Rm. 157 - Girl's Bathroom	Sink	Public Access	SR-039	SR-S321	< 1.0	None
Rm. 157 - Girl's Bathroom	Sink	Public Access	SR-040	SR-S322	< 1.0	None
Rm. 158 - Boy's Bathroom	Sink	Public Access	SR-036	SR-S318	< 1.0	None
Rm. 158 - Boy's Bathroom	Sink	Public Access	SR-037	SR-S319	2.2	None
Rm. 158 - Boy's Bathroom	Sink	Public Access	SR-038	SR-S320	1.9	None

SYRACUSE CITY SCHOOL DISTRICT
SEYMOUR DUAL LANGUAGE ACADEMY SCHOOL PK-GRADE 5

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 12/02/2016, 12/03/2016 and 12/04/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 159 - Office Bathroom	Sink	Secured - SCSD Staff Only	SR-042	SR-S324	< 1.0	None
Rm. 160A - Office Bathroom	Sink	Secured - SCSD Staff Only	SR-041	SR-S323	2.4	None
Rm. 174 - Nurse's Bathroom	Sink	Public Access	SR-045	SR-S327	< 1.0	None
Rm. 175 - Exam Room	Sink	Public Access	SR-044	SR-S326	1.7	None
Rm. 176 - Cafeteria	Fountain	Public Access	SR-057	SR-F305	< 1.0	None
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	SR-011	SR-S210	< 1.0	None
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	SR-012	SR-S211	< 1.0	None
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	SR-013	SR-S212	< 1.0	None
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	SR-014	SR-S213	350.0	SCSD permanently removed fixture from service
Rm. 182 - Staff Bathroom	Sink	Secured - SCSD Staff Only	SR-043	SR-S325	< 1.0	None
Rm. 216 - Classroom Bathroom	Sink	Public Access	SR-030	SR-S312	< 1.0	None
Rm. 221 - Teacher's Lounge	Sink	Secured - SCSD Staff Only	SR-033	SR-S315	< 1.0	None
Rm. 221B - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	SR-031	SR-S313	< 1.0	None
Rm. 221C - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	SR-032	SR-S314	< 1.0	None
Rm. 221G - Hallway/Vestibule	Fountain	Public Access	SR-054	SR-F302	< 1.0	None
Rm. 221G - Hallway/Vestibule	Sink	Public Access	SR-025	SR-S307	< 1.0	None
Rm. 221G - Hallway/Vestibule	Sink	Public Access	SR-026	SR-S308	1.3	None
Rm. 222A - Classroom	Sink	Public Access	SR-027	SR-S309	< 1.0	None
Rm. 227 - Art Room	Sink	Public Access	SR-028	SR-S310	< 1.0	None
Rm. 227 - Art Room	Sink	Public Access	SR-029	SR-S311	< 1.0	None
Rm. 232 - Hallway/Corridor	Fountain	Public Access	SR-053	SR-F301	< 1.0	None
Rm. 242 - Girl's Bathroom	Sink	Public Access	SR-022	SR-S304	< 1.0	None
Rm. 242 - Girl's Bathroom	Sink	Public Access	SR-023	SR-S305	< 1.0	None
Rm. 242 - Girl's Bathroom	Sink	Public Access	SR-024	SR-S306	< 1.0	None
Rm. 245 - Boy's Bathroom	Sink	Public Access	SR-019	SR-S301	< 1.0	None
Rm. 245 - Boy's Bathroom	Sink	Public Access	SR-020	SR-S302	< 1.0	None
Rm. 245 - Boy's Bathroom	Sink	Public Access	SR-021	SR-S303	2.0	None
Rm. 251 - Staff Bathroom	Sink	Secured - SCSD Staff Only	SR-034	SR-S316	< 1.0	None

SYRACUSE CITY SCHOOL DISTRICT
SEYMOUR DUAL LANGUAGE ACADEMY SCHOOL PK-GRADE 5

SAMPLE DATE: 09/24/2016 ANALYSIS DATES: 12/02/2016, 12/03/2016 and 12/04/2016

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-017
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1616297
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.