

SYRACUSE CITY SCHOOL DISTRICT
LINCOLN MIDDLE SCHOOL

SAMPLE DATE: 10/07/2016 ANALYSIS DATES: 12/15/2016, 12/16/2016 and 12/18/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 101 - Hallway/Corridor	Fountain	Public Access	LN-084	LN-F205	< 1.0	None
Rm. 101 - Hallway/Corridor	Fountain	Public Access	LN-085	LN-F206	< 1.0	None
Rm. 101D - Hallway/Corridor	Fountain	Public Access	LN-091	LN-F404	< 1.0	None
Rm. 101H - Hallway/Corridor	Fountain	Public Access	LN-080	LN-F201	< 1.0	None
Rm. 102 - Nurse's Office	Sink	Public Access	LN-024	LN-S223	2.0	None
Rm. 102B - Clinic Office Bathroom	Sink	Public Access	LN-025	LN-S224	2.9	None
Rm. 102C - Nurse's Office Bathroom	Sink	Public Access	LN-023	LN-S222	1.7	None
Rm. 103 - Home & Careers Room	Sink	Public Access	LN-063	LN-S428	2.9	None
Rm. 103 - Home & Careers Room	Sink	Public Access	LN-064	LN-S429	1.7	None
Rm. 104 - Classroom	Sink	Public Access	LN-065	LN-S430	5.2	None
Rm. 104 - Classroom	Sink	Public Access	LN-066	LN-S431	3.0	None
Rm. 104 - Classroom	Sink	Public Access	LN-067	LN-S432	1.9	None
Rm. 105 - Art Room	Sink	Public Access	LN-068	LN-S433	5.3	None
Rm. 105 - Art Room	Sink	Public Access	LN-069	LN-S434	4.3	None
Rm. 106A - Storage Room	Sink	Secured - SCSD Staff Only	LN-070	LN-S435	< 1.0	None
Rm. 107 - Classroom	Sink	Public Access	LN-071	LN-S436	1.7	None
Rm. 107 - Classroom	Sink	Public Access	LN-072	LN-S437	< 1.0	None
Rm. 109F - Kitchen	Sink	Secured - SCSD Staff Only	LN-026	LN-S225	< 1.0	None
Rm. 109F - Kitchen	Sink	Secured - SCSD Staff Only	LN-027	LN-S226	< 1.0	None
Rm. 109F - Kitchen	Sink	Secured - SCSD Staff Only	LN-028	LN-S227	1.1	None
Rm. 109F - Kitchen	Sink	Secured - SCSD Staff Only	LN-029	LN-S228	< 1.0	None
Rm. 109F - Kitchen	Sink	Secured - SCSD Staff Only	LN-030	LN-S229	< 1.0	None
Rm. 109F - Kitchen	Sink	Secured - SCSD Staff Only	LN-031	LN-S230	12.0	None
Rm. 109F - Kitchen	Kettle	Secured - SCSD Staff Only	LN-033	LN-S232	< 1.0	None
Rm. 109F - Kitchen	Kettle	Secured - SCSD Staff Only	LN-034	LN-S233	1.4	None
Rm. 109F - Kitchen	Steam Rack Nozzle	Secured - SCSD Staff Only	LN-035	LN-S234	< 1.0	None
Rm. 109F - Kitchen	Ice Machine	Secured - SCSD Staff Only	LN-036	LN-S235	< 1.0	None
Rm. 109G - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	LN-021	LN-S220	1.5	None
Rm. 109H - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	LN-020	LN-S219	1.4	None

**SYRACUSE CITY SCHOOL DISTRICT
LINCOLN MIDDLE SCHOOL**

SAMPLE DATE: 10/07/2016 ANALYSIS DATES: 12/15/2016, 12/16/2016 and 12/18/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 110 - Boy's Bathroom	Sink	Public Access	LN-077	LN-S442	1.3	None
Rm. 110 - Boy's Bathroom	Sink	Public Access	LN-078	LN-S443	2.0	None
Rm. 110 - Boy's Bathroom	Sink	Public Access	LN-079	LN-S444	< 1.0	None
Rm. 110A - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	LN-032	LN-S231	1.4	None
Rm. 111 - Girl's Bathroom	Sink	Public Access	LN-073	LN-S438	< 1.0	None
Rm. 111 - Girl's Bathroom	Sink	Public Access	LN-074	LN-S439	< 1.0	None
Rm. 111 - Girl's Bathroom	Sink	Public Access	LN-075	LN-S440	1.5	None
Rm. 111 - Girl's Bathroom	Sink	Public Access	LN-076	LN-S441	1.5	None
Rm. 113 - Wood Shop	Sink	Public Access	LN-037	LN-S236	5.4	None
Rm. 115 - Art Room	Sink	Public Access	LN-038	LN-S237	1.8	None
Rm. 115 - Art Room	Sink	Public Access	LN-039	LN-S238	3.0	None
Rm. 119A - Gym	Fountain	Public Access	LN-083	LN-F204	1.0	None
Rm. 119A - Gym	Fountain	Public Access	LN-081	LN-F202	1.5	None
Rm. 123 - Mechanical/Meter Room	Hose Bib at Meter Assembly	Secured - SCSD Staff Only	LN-001	LN-M200	15.0	SCSD to post warning sign
Rm. 125 - Office	Sink	Secured - SCSD Staff Only	LN-040	LN-S239	3.2	None
Rm. 128 - Library	Fountain	Public Access	LN-087	LN-F208	< 1.0	None
Rm. 128A - Library Office	Sink	Secured - SCSD Staff Only	LN-022	LN-S221	< 1.0	None
Rm. 130 - Boy's Bathroom	Sink	Public Access	LN-009	LN-S208	1.3	None
Rm. 130 - Boy's Bathroom	Sink	Public Access	LN-010	LN-S209	1.9	None
Rm. 130 - Boy's Bathroom	Sink	Public Access	LN-011	LN-S210	2.7	None
Rm. 130 - Boy's Bathroom	Sink	Public Access	LN-012	LN-S211	1.7	None
Rm. 132 - Girl's Locker Room	Fountain	Public Access	LN-082	LN-F203	17.0	SCSD removed fixture from service and is to replace
Rm. 132A - Girl's Coach Office Bathroom	Sink	Secured - SCSD Staff Only	LN-008	LN-S207	22.0	SCSD removed fixture from service and is to replace
Rm. 132B - Girl's Bathroom	Sink	Public Access	LN-013	LN-S212	1.0	None
Rm. 132B - Girl's Bathroom	Sink	Public Access	LN-014	LN-S213	2.1	None
Rm. 132B - Girl's Bathroom	Sink	Public Access	LN-015	LN-S214	1.7	None
Rm. 132B - Girl's Bathroom	Sink	Public Access	LN-016	LN-S215	34.0	SCSD removed fixture from service and is to replace
Rm. 132B - Girl's Bathroom	Sink	Public Access	LN-017	LN-S216	10.0	None
Rm. 132B - Girl's Bathroom	Sink	Public Access	LN-018	LN-S217	2.1	None

**SYRACUSE CITY SCHOOL DISTRICT
LINCOLN MIDDLE SCHOOL**

SAMPLE DATE: 10/07/2016 ANALYSIS DATES: 12/15/2016, 12/16/2016 and 12/18/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 132B - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	LN-019	LN-S218	1.9	None
Rm. 132E - Girl's Locker Room Bathroom	Sink	Public Access	LN-005	LN-S204	< 1.0	None
Rm. 132E - Girl's Locker Room Bathroom	Sink	Public Access	LN-006	LN-S205	< 1.0	None
Rm. 132E - Girl's Locker Room Bathroom	Sink	Public Access	LN-007	LN-S206	1.9	None
Rm. 133A - Boy's Coach Office Bathroom	Sink	Secured - SCSD Staff Only	LN-004	LN-S203	2.7	None
Rm. 133E - Boy's Locker Room Bathroom	Sink	Public Access	LN-002	LN-S201	1.6	None
Rm. 133E - Boy's Locker Room Bathroom	Sink	Public Access	LN-003	LN-S202	2.2	None
Rm. 134A - Hallway/Corridor	Fountain	Public Access	LN-086	LN-F207	< 1.0	None
Rm. 206A - Hallway/Corridor	Fountain	Public Access	LN-090	LN-F402	< 1.0	None
Rm. 206A - Hallway/Corridor	Fountain	Public Access	--	LN-F403	--	Fixture not operating
Rm. 207 - Hallway/Corridor	Sink	Public Access	LN-089	LN-F401	< 1.0	None
Rm. 212 - Laboratory Room	Sink	Public Access	--	LN-S421	--	Fixture not operating
Rm. 212 - Laboratory Room	Sink	Public Access	--	LN-S422	--	Fixture not operating
Rm. 226 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	LN-041	LN-S400	25.0	SCSD removed fixture from service and is to replace
Rm. 227 - Girl's Bathroom	Sink	Public Access	LN-042	LN-S401	1.6	None
Rm. 227 - Girl's Bathroom	Sink	Public Access	LN-043	LN-S402	1.2	None
Rm. 227 - Girl's Bathroom	Sink	Public Access	LN-044	LN-S403	1.5	None
Rm. 227 - Girl's Bathroom	Sink	Public Access	LN-045	LN-S404	1.6	None
Rm. 213 - Hallway/Corridor	Fountain	Public Access	LN-088	LN-F400	< 1.0	None
Rm. 215 - Laboratory Room	Sink	Public Access	LN-059	LN-S423	14.0	None
Rm. 215 - Laboratory Room	Sink	Public Access	LN-060	LN-S424	30.0	SCSD permanently removed fixture from service
Rm. 215 - Laboratory Room	Sink	Public Access	LN-061	LN-S425	6.5	None
Rm. 215 - Laboratory Room	Sink	Public Access	--	LN-S426	--	Fixture not operating
Rm. 215A - Laboratory Storage Room	Sink	Public Access	LN-062	LN-S427	27.0	SCSD permanently removed fixture from service
Rm. 224 - Laboratory Room	Sink	Public Access	--	LN-S410	--	Fixture not operating
Rm. 224 - Laboratory Room	Sink	Public Access	--	LN-S411	--	Fixture not operating
Rm. 224 - Laboratory Room	Sink	Public Access	LN-050	LN-S412	3.1	None
Rm. 224 - Laboratory Room	Sink	Public Access	LN-051	LN-S413	9.5	None
Rm. 224 - Laboratory Room	Sink	Public Access	LN-052	LN-S414	5.7	None

**SYRACUSE CITY SCHOOL DISTRICT
LINCOLN MIDDLE SCHOOL**

SAMPLE DATE: 10/07/2016 ANALYSIS DATES: 12/15/2016, 12/16/2016 and 12/18/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 236 - Laboratory Room	Sink	Public Access	LN-046	LN-S405	21.0	SCSD permanently removed fixture from service
Rm. 236 - Laboratory Room	Sink	Public Access	LN-047	LN-S406	16.0	SCSD permanently removed fixture from service
Rm. 236 - Laboratory Room	Sink	Public Access	LN-048	LN-S407	17.0	SCSD permanently removed fixture from service
Rm. 236 - Laboratory Room	Sink	Public Access	--	LN-S408	--	Fixture not operating
Rm. 236A - Laboratory Storage Room	Sink	Public Access	LN-049	LN-S409	7.4	None
Rm. 242 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	LN-053	LN-S415	1.9	None
Rm. 242A - Storage Room	Sink	Secured - SCSD Staff Only	LN-058	LN-S420	2.9	None
Rm. 242B - Boy's Bathroom	Sink	Public Access	LN-054	LN-S416	1.7	None
Rm. 242B - Boy's Bathroom	Sink	Public Access	LN-055	LN-S417	1.3	None
Rm. 242B - Boy's Bathroom	Sink	Public Access	LN-056	LN-S418	< 1.0	None
Rm. 242B - Boy's Bathroom	Sink	Public Access	LN-057	LN-S419	2.2	None

Notes:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-026
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1620567
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.