

**SYRACUSE CITY SCHOOL DISTRICT
ELMWOOD ELEMENTARY SCHOOL**

SAMPLE DATE: 10/27/2016 ANALYSIS DATES: 12/27/2016 and 12/28/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	--	ELM-S201	--	Fixture not operating
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	ELM-026	ELM-S202	23.0	SCSD removed fixture from service and is to replace
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	ELM-027	ELM-S203	70.0	SCSD removed fixture from service and is to replace
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	--	ELM-S204	--	Fixture not operating
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	ELM-028	ELM-S205	23.0	SCSD removed fixture from service and is to replace
Rm. 08 - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	ELM-025	ELM-M(S)200	5.3	None
Rm. 31A - Custodian's Bathroom	Sink	Secured - SCSD Staff Only	ELM-032	ELM-S211	1.9	None
Rm. 40 - Hallway/Vestibule	Fountain	Public Access	ELM-058	ELM-F201	1.1	None
Rm. 40 - Hallway/Vestibule	Sink	Public Access	--	ELM-S206	--	Fixture not operating
Rm. 40 - Hallway/Vestibule	Sink	Public Access	ELM-029	ELM-S207	20.0	SCSD removed fixture from service and is to replace
Rm. 40 - Hallway/Vestibule	Sink	Public Access	ELM-030	ELM-S208	5.1	None
Rm. 42 - Boy's Bathroom	Sink	Public Access	--	ELM-S210	--	Fixture not operating
Rm. 44 - Girl's Bathroom	Sink	Public Access	ELM-031	ELM-S209	32.0	SCSD removed fixture from service and is to replace
Rm. 47 - Staff Bathroom	Sink	Secured - SCSD Staff Only	ELM-008	ELM-S109	44.0	SCSD removed fixture from service and is to replace
Rm. 55 - Gym Office Bathroom	Sink	Secured - SCSD Staff Only	ELM-005	ELM-S106	19.0	SCSD removed fixture from service and is to replace
Rm. 59 - Classroom	Sink	Public Access	ELM-001	ELM-S100	1.1	None
Rm. 59 - Classroom	Sink	Public Access	ELM-002	ELM-S101	12.0	None
Rm. 61 - Classroom	Sink	Public Access	ELM-003	ELM-S102	5.6	None
Rm. 61 - Classroom	Sink	Public Access	ELM-004	ELM-S103	3.7	None
Rm. 63 - Classroom	Sink	Public Access	ELM-006	ELM-S107	17.0	SCSD removed fixture from service and is to replace
Rm. 63 - Classroom	Sink	Public Access	ELM-007	ELM-S108	18.0	SCSD removed fixture from service and is to replace
Rm. 68 - Storage Room	Sink	Secured - SCSD Staff Only	--	ELM-S105	--	Fixture not operating
Rm. 69 - PT Office	Sink	Secured - SCSD Staff Only	--	ELM-S104	--	Fixture not operating
Rm. 105 - Resource Room	Sink	Public Access	ELM-021	ELM-S125	43.0	SCSD removed fixture from service and is to replace
Rm. 106 - Teacher's Lounge	Sink	Secured - SCSD Staff Only	ELM-019	ELM-S122	1.9	None
Rm. 107 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	ELM-020	ELM-S124	9.2	None
Rm. 109 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	--	ELM-S123	--	Fixture not operating
Rm. 121A - Parent Room	Sink	Secured - SCSD Staff Only	ELM-016	ELM-S119	2.4	None
Rm. 124 - Hallway/Vestibule	Fountain	Public Access	ELM-022	ELM-F101	< 1.0	None

**SYRACUSE CITY SCHOOL DISTRICT
ELMWOOD ELEMENTARY SCHOOL**

SAMPLE DATE: 10/27/2016 ANALYSIS DATES: 12/27/2016 and 12/28/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 124 - Hallway/Vestibule	Sink	Public Access	ELM-013	ELM-S115	11.0	None
Rm. 124 - Hallway/Vestibule	Sink	Public Access	ELM-014	ELM-S116	15.0	SCSD removed fixture from service and is to replace
Rm. 124 - Hallway/Vestibule	Sink	Public Access	ELM-015	ELM-S117	2.6	None
Rm. 125 - Boy's Bathroom	Sink	Public Access	--	ELM-S118	--	Fixture not operating
Rm. 126 - Girl's Bathroom	Sink	Public Access	--	ELM-S114	--	Fixture not operating
Rm. 133 - Staff Bathroom	Sink	Public Access	ELM-037	ELM-S216	4.2	None
Rm. 134 - Classroom	Sink	Public Access	ELM-033	ELM-S212	9.7	None
Rm. 135 - Classroom Bathroom	Sink	Public Access	ELM-034	ELM-S213	1.8	None
Rm. 136 - Classroom	Sink	Public Access	ELM-035	ELM-S214	13.0	None
Rm. 137 - Classroom	Sink	Public Access	ELM-036	ELM-S215	34.0	SCSD removed fixture from service and is to replace
Rm. 138 - Classroom	Sink	Public Access	ELM-038	ELM-S217	8.8	None
Rm. 139 - Hallway/Corridor	Fountain	Public Access	ELM-023	ELM-F102	< 1.0	None
Rm. 139 - Hallway/Corridor	Fountain	Public Access	ELM-024	ELM-F103	< 1.0	None
Rm. 142A - Classroom	Sink	Public Access	ELM-012	ELM-S113	3.8	None
Rm. 142A - Classroom	Fountain	Public Access	--	ELM-F100	--	Fixture not operating
Rm. 142B - Resource Room	Sink	Public Access	ELM-009	ELM-S110	31.0	SCSD removed fixture from service and is to replace
Rm. 146 - Classroom	Sink	Public Access	ELM-010	ELM-S111	3.7	None
Rm. 146 - Classroom	Sink	Public Access	ELM-011	ELM-S112	5.7	None
Rm. 153 - Nurse's Office Bathroom	Sink	Public Access	ELM-018	ELM-S121	2.4	None
Rm. 156 - Main Office Bathroom	Sink	Secured - SCSD Staff Only	ELM-017	ELM-S120	6.8	None
Rm. 205 - Staff Bathroom	Sink	Secured - SCSD Staff Only	ELM-048	ELM-S228	4.4	None
Rm. 208 - Classroom	Sink	Public Access	ELM-052	ELM-S232	11.0	None
Rm. 212 - Work Room	Sink	Secured - SCSD Staff Only	ELM-057	ELM-S237	4.2	None
Rm. 215 - Hallway/Vestibule	Sink	Public Access	ELM-053	ELM-S233	15.0	SCSD removed fixture from service and is to replace
Rm. 215 - Hallway/Vestibule	Sink	Public Access	ELM-054	ELM-S234	9.8	None
Rm. 215 - Hallway/Vestibule	Sink	Public Access	ELM-055	ELM-S235	7.7	None
Rm. 215 - Hallway/Vestibule	Sink	Public Access	ELM-056	ELM-S236	3.8	None
Rm. 215 - Hallway/Vestibule	Fountain	Public Access	ELM-060	ELM-F203	< 1.0	None
Rm. 221 - Classroom	Sink	Public Access	ELM-051	ELM-S231	9.3	None

**SYRACUSE CITY SCHOOL DISTRICT
ELMWOOD ELEMENTARY SCHOOL**

SAMPLE DATE: 10/27/2016 ANALYSIS DATES: 12/27/2016 and 12/28/2016

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
Rm. 224 - Classroom	Sink	Public Access	ELM-044	ELM-S223	12.0	None
Rm. 225 - Classroom	Sink	Public Access	ELM-041	ELM-S220	65.0	SCSD removed fixture from service and is to replace
Rm. 226 - Classroom	Sink	Public Access	ELM-039	ELM-S218	14.0	None
Rm. 227 - Classroom	Sink	Public Access	ELM-040	ELM-S219	3.1	None
Rm. 228 - Classroom	Sink	Public Access	ELM-042	ELM-S221	6.0	None
Rm. 229 - Classroom	Sink	Public Access	ELM-043	ELM-S222	20.0	SCSD removed fixture from service and is to replace
Rm. 230 - Hallway/Vestibule	Fountain	Public Access	ELM-059	ELM-F202	< 1.0	None
Rm. 230 - Hallway/Vestibule	Sink	Public Access	ELM-045	ELM-S224	27.0	SCSD removed fixture from service and is to replace
Rm. 230 - Hallway/Vestibule	Sink	Public Access	ELM-046	ELM-S225	62.0	SCSD removed fixture from service and is to replace
Rm. 230 - Hallway/Vestibule	Sink	Public Access	--	ELM-S226	--	Fixture out of service
Rm. 230 - Hallway/Vestibule	Sink	Public Access	ELM-047	ELM-S227	68.0	SCSD removed fixture from service and is to replace
Rm. 233 - Classroom	Sink	Public Access	ELM-049	ELM-S229	11.0	None
Rm. 235 - Classroom	Sink	Public Access	ELM-050	ELM-S230	9.0	None

Notes:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-042
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1621047
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. This school facility is currently vacant. Resampling of fixture locations where exceedances were discovered will be performed prior to re-occupancy.