

SYRACUSE CITY SCHOOL DISTRICT
McCARTHY AT BEARD SPECIAL EDUCATION SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	09/23/16 SAMPLE RESULTS (ppb)	09/23/16 ORIGINAL ACTIONS	11/10/17 SAMPLE RESULTS (ppb)	11/10/17 ORIGINAL ACTIONS
Rm. B005 - Mechanical/Meter Room	Hose Bib at Meter	Secured - SCSD Staff Only	BD-001	BD-M100	3.1	None	--	--
Rm. 101A - Teacher's Lounge	Sink	Secured - SCSD Staff Only	BD-006	BD-S100	1.7	None	--	--
Rm. 101A - Kitchen	Sink	Secured - SCSD Staff Only	BD-014	BD-S108	3.0	None	--	--
Rm. 101A - Kitchen	Sink	Secured - SCSD Staff Only	BD-015	BD-S109	< 1.0	None	--	--
Rm. 101A - Kitchen	Sink	Secured - SCSD Staff Only	BD-016	BD-S110	< 1.0	None	--	--
Rm. 108 - Boy's Bathroom	Sink	Public Access	BD-017	BD-S111	2.7	None	--	--
Rm. 108 - Boy's Bathroom	Sink	Public Access	BD-018	BD-S112	1.4	None	--	--
Rm. 110 - Hallway/Corridor	Fountain	Public Access	BD-004	BD-F103	5.7	None	--	--
Rm. 111B - Clinic Room	Sink	Public Access	BD-012	BD-S106	1.8	None	--	--
Rm. 111C - Clinic Bathroom	Sink	Public Access	BD-013	BD-S107	< 1.0	None	--	--
Rm. 112 - Boy's Bathroom	Sink	Public Access	BD-008	BD-S102	1.1	None	--	--
Rm. 113 - Girl's Bathroom	Sink	Public Access	BD-009	BD-S103	1.0	None	--	--
Rm. 114D - Office Bathroom	Sink	Secured - SCSD Staff Only	BD-010	BD-S104	2.6	None	--	--
Rm. 129 - Hallway/Corridor	Fountain	Public Access	BD-002	BD-F100	1.9	None	--	--
Rm. 137 - Men's Bathroom	Sink	Secured - SCSD Staff Only	BD-007	BD-S101C	< 1.0	None	--	--
Rm. 158 - Storage Room Bathroom	Bathroom Sink	Secured - SCSD Staff Only	BD-011	BD-S105	14.0	None	--	--
Rm. 163 - Hallway/Corridor	Fountain	Public Access	BD-003	BD-F102	< 1.0	None	--	--
Rm. 210 - Boy's Bathroom	Sink	Public Access	BD-022	BD-S116	< 1.0	None	--	--
Rm. 210 - Boy's Bathroom	Sink	Public Access	BD-023	BD-S117	1.2	None	--	--
Rm. 211 - Girl's Bathroom	Sink	Public Access	BD-021	BD-S115	27.0	SCSD to replace fixture	1.4	None
Rm. 211 - Girl's Bathroom	Sink	Public Access	BD-021	BD-S119	--	--	<1.0	None; See Note 5
Rm. 217 - Boy's Bathroom	Sink	Public Access	BD-019	BD-S113	5.0	None	--	--
Rm. 217 - Boy's Bathroom	Sink	Public Access	BD-020	BD-S114	1.2	None	--	--
Rm. 223 - Hallway/Corridor	Fountain	Public Access	BD-005	BD-F104	40.0	SCSD to replace fixture	<1.0	None
Rm. 239 - Staff Bathroom	Bathroom Sink	Secured - SCSD Staff Only	BD-024	BD-S118	1.7	None	--	--

Original Sampling Notes (September 23, 2016):

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-012
2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID No. 1616195
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.

Resampling Notes (November 10, 2017 Event):

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-042
2. Water samples analyzed by: Life Science Laboratories, Inc. - LSL Project ID No. 1718690; November 20, 2017
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
5. A new sink was installed within this bathroom.