

SYRACUSE CITY SCHOOL DISTRICT
McCARTHY AT BEARD SPECIAL EDUCATION SCHOOL
SAMPLE DATE: 10/11/23 ANALYSIS DATE: 10/16/23

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	10/11/23 RESULTS (ppb)	10/11/23 ACTIONS
Rm. 101A - Teacher's Lounge	Sink	Secured - SCSD Staff Only	001	MD-S100	3.2	None
Rm. 101A - Kitchen	Sink	Secured - SCSD Staff Only	008	MD-S108	2.3	None
Rm. 101A - Kitchen	Sink	Secured - SCSD Staff Only	---	MD-S109	---	See Note 6.
Rm. 110 - Hallway/Corridor	Fountain	Public Access	---	MD-F103	---	See Note 7.
Rm. 111B - Clinic Room	Sink	Public Access	007	MD-S106	2.1	None
Rm. 129 - Hallway/Corridor	Fountain	Public Access	003	MD-F100	<1.0	None
Rm. 129 - Hallway/Corridor	Fountain (Sensor)	Public Access	002	MD-F100A	<1.0	None
Rm. 163 - Hallway/Corridor	Fountain	Public Access	006	MD-F102	<1.0	None
Rm. 223 - Hallway/Corridor	Fountain	Public Access	010	MD-F104	<1.0	None
Rm. 115 - Official Meeting Room	Sink	Public Access	004	MD-S1000	<1.0	None
Rm. 115 - Official Meeting Room	Sink (Sprayer)	Public Access	005	MD-S1000A	<1.0	None
Rm. 101A - Kitchen	Sink	Secured - SCSD Staff Only	009	MD-S110	<1.0	None

Notes [October 11, 2023 Event]:

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-011
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project No. (70273798)
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture inoperative. SCSD to evaluate for repair or removal.
7. Fixture removed by SCSD.