

SYRACUSE CITY SCHOOL DISTRICT
NOTTINGHAM HIGH SCHOOL
SAMPLE DATE: 02/16/24 ANALYSIS DATE: 02/21/24

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	02/16/24 RESULTS (ppb)	02/16/24 ACTIONS
BUILDING 'A'						
Rm. 46 - Kitchen	Sink	Secured - SCSD Staff Only	015	NM-S131	2.5	None
Rm. 46 - Kitchen	Sink (Hose)	Secured - SCSD Staff Only	014	NM-S132	2.2	None
Rm. 46 - Kitchen	Sink (Hose)	Secured - SCSD Staff Only	013	NM-S133	1.8	None
Rm. 46 - Kitchen	Sink	Secured - SCSD Staff Only	012	NM-S134	6.9	See Note 6.
Rm. 46 - Kitchen	Sink	Secured - SCSD Staff Only	010	NM-S136	2.0	None
Rm. 46 - Kitchen	Sink	Secured - SCSD Staff Only	011	NM-S137	2.0	None
Rm. 46 - Kitchen	Sink	Secured - SCSD Staff Only	018	NM-S139	3.4	None
Rm. 46 - Kitchen	Sink (Hose)	Secured - SCSD Staff Only	017	NM-S142	45.3	See Note 7.
Rm. 46 - Kitchen	Sink (Hose)	Secured - SCSD Staff Only	057	NM-S143	6.1	See Note 9.
Rm. 46 - Kitchen	Ice Machine	Secured - SCSD Staff Only	016	NM-S149	<1.0	None
Hallway/Corridor - C203	Fountain	Public Access	001	NM-F1006	<1.0	None
Hallway/Corridor - C203	Fountain	Public Access	002	NM-F1007	1.0	None
Hallway/Corridor - C204	Fountain	Public Access	003	NM-F1008	<1.0	None
Hallway/Corridor - C204	Fountain	Public Access	004	NM-F1009	<1.0	None
Hallway/Corridor - C116	Fountain	Public Access	005	NM-F1004	<1.0	None
Hallway/Corridor - C116	Fountain	Public Access	006	NM-F1005	<1.0	None
Hallway/Corridor - C115	Fountain	Public Access	007	NM-F1002	<1.0	None
Hallway/Corridor - C115	Fountain	Public Access	008	NM-F1003	<1.0	None
Hallway/Corridor - C106	Fountain	Public Access	009	NM-F202	3.8	None
Rm. 46 - Kitchen	Combitherm	Secured - SCSD Staff Only	019	NM-C1000	5.9	See Note 6.
Rm. 46 - Kitchen	Combitherm	Secured - SCSD Staff Only	020	NM-C1001	1.8	None
Rm. 46 - Kitchen	Convotharm	Secured - SCSD Staff Only	021	NM-C1002	4.4	None
Hallway/Corridor - C107	Fountain	Public Access	023	NM-F1000	<1.0	None
Hallway/Corridor - C107	Fountain	Public Access	024	NM-F1001	2.2	None
Hallway/Corridor - C107	Fountain (Sensor)	Public Access	025	NM-F1001 A	<1.0	None
Rm. 102 - Life Skills	Sink	Public Access	051	NM-S1004	<1.0	None
Rm. 102 - Life Skills	Sink	Public Access	052	NM-S1003	<1.0	None
Rm. 24 - Work Area	Sink	Public Access	053	NM-S1002	<1.0	None

SYRACUSE CITY SCHOOL DISTRICT
 NOTTINGHAM HIGH SCHOOL
 SAMPLE DATE: 02/16/24 ANALYSIS DATE: 02/21/24

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	02/16/24 RESULTS (ppb)	02/16/24 ACTIONS
BUILDING 'A' Cont.						
Rm. 23 - Exam	Sink	Public Access	054	NM-S1001	1.7	None
Rm. 11 - Main Office	Sink	Secured - SCSD Staff Only	055	NM-S1000	<1.0	None
Rm. 46 - Kitchen	Sink	Secured - SCSD Staff Only	056	NM-S135	2.1	None
Hallway/Corridor - C113	Fountain	Public Access	026	NM-F205	2.3	None
Hallway/Corridor - C113	Fountain	Public Access	027	NM-F206	1.3	None
Rm. 69 - Ice/Laundry	Ice Machine	Public Access	028	NM-S253	<1.0	None
Hallway/Lobby - C109	Fountain	Public Access	022	NM-F208	2.4	None

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	02/16/24 RESULTS (ppb)	02/16/24 ACTIONS
BUILDING 'B'						
Rm. GW3 - Classroom Bathroom	Sink	Public Access	041	NM-S115	5.6	See Note 8.
Rm. GW5 - Classroom Bathroom	Sink	Public Access	042	NM-S114	4.4	None
Rm. GW6 - Classroom Bathroom	Sink	Public Access	043	NM-S112	3.2	None
Rm. GW7 - Classroom Bathroom	Sink	Public Access	044	NM-S109	3.8	None
Rm. GW9 - Classroom	Sink	Public Access	045	NM-S106	3.7	None
Rm. GW11 - Classroom Bathroom	Sink	Public Access	046	NM-S102	1.7	None
Rm. GW13 - Office	Sink	Secured - SCSD Staff Only	032	NM-S126	4.1	None
Rm. GW14 - Office	Sink	Secured - SCSD Staff Only	033	NM-S124	5.0	None
Hallway/Corridor - C125	Fountain	Public Access	035	NM-F101A	<1.0	None
Hallway/Corridor - C125	Fountain	Public Access	034	NM-F101B	<1.0	None
Rm. GW21 - Shop	Sink	Public Access	030	NM-S2001	4.8	None
Hallway/Corridor - C127	Fountain	Public Access	031	NM-F2000	<1.0	None
Rm. GW4 - Project L.T.W. Classroom	Sink	Public Access	036	NM-S2010	6.6	See Note 7.
Rm. GW4 - Project L.T.W. Classroom	Sink	Public Access	037	NM-S2011	2.6	None
Rm. GW4 - Project L.T.W. Classroom	Sink	Public Access	038	NM-S2012	1.1	None
Rm. GW4 - Project L.T.W. Classroom	Sink	Public Access	039	NM-S2007	2.6	None

**SYRACUSE CITY SCHOOL DISTRICT
NOTTINGHAM HIGH SCHOOL**
SAMPLE DATE: 02/16/24 ANALYSIS DATE: 02/21/24

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	02/16/24 RESULTS (ppb)	02/16/24 ACTIONS
BUILDING 'B' Cont.						
Rm. GW4 - Project L.T.W. Classroom	Sink	Public Access	040	NM-S2008	2.6	None
Hallway/Lobby - C120	Fountain	Public Access	048	NM-F2001	<1.0	None
Hallway/Lobby - C120	Fountain	Public Access	049	NM-F2002	<1.0	None
Rm. GW21 - Shop	Sink	Public Access	029	NM-S2001 A	2.9	None
Hallway/Lobby - C120	Fountain	Public Access	047	NM-F321	8.3	See Note 7.
Rm. P-137 - Swimming Pool Area	Fountain	Public Access	050	NM-F328	1.7	None

Notes [February 16, 2024 Event]:

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-028.
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project No. 70287757.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture repaired by SCSD. Resampling pending.
7. Fixture removed by SCSD.
8. Fixture signed by SCSD. No further action required.
9. Fixture repair in progress (replacement part on backorder). Resampling pending completion.