

**SYRACUSE CITY SCHOOL DISTRICT  
HUNTINGTON PK- GRADE 8 SCHOOL**

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	07/28/23 RESULTS (ppb)	07/28/23 ACTIONS	LAB RE-SAMPLE I.D. No.	03/27/24 RE-SAMPLE RESULTS (ppb)	03/27/24 RE-SAMPLE ACTIONS
Rm. A102 - Hallway/Corridor	Fountain	Public Access	030	HN-F200	<1.0	None	---	---	---
Rm. A102 - Hallway/Corridor	Fountain (Sensor)	Public Access	031	HN-F200A	<1.0	None	---	---	---
Pool	Fountain	Public Access	017	HN-F602	<1.0	None	---	---	---
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	032	HN-S201	2.5	None	---	---	---
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	033	HN-S202	1.1	None	---	---	---
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	034	HN-S203	2.1	None	---	---	---
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	035	HN-S204	3.9	None	---	---	---
Rm. A112 - Kitchen	Sink	Secured - SCSD Staff Only	036	HN-S205	9.4	See Note 7.	002	3.7	None
Rm. A112 - Kitchen	Cooker Spray	Secured - SCSD Staff Only	038	HN-B	15.8	See Note 6.	001	4.4	None
Rm. A112 - Kitchen	Cooker Spray	Secured - SCSD Staff Only	037	HN-A	<1.0	None	---	---	---
Rm. A139 - Gym	Fountain	Public Access	019	HN-F201	<1.0	None	---	---	---
Rm. A139 - Gym	Fountain	Public Access	018	HN-F202	<1.0	None	---	---	---
Rm. A240 - Classroom	Sink	Public Access	029	HN-S223	3.2	None	---	---	---
Rm. B02 - Hallway/Corridor	Fountain (Lower/Right)	Public Access	004	HN-F501	<1.0	None	---	---	---
Rm. B02 - Hallway/Corridor	Fountain (Upper/Left)	Public Access	003	HN-F500	<1.0	None	---	---	---
Rm. B03 OTPT	Main Sink	Public Access	---	HN-S500	---	See Note 6.	003	1.5	None
Rm. B06 - Art Room	Main Sink	Public Access	005	HN-S506	2.6	None	---	---	---
Rm. B10 - Hallway/Corridor	Fountain (Upper/Left)	Public Access	002	HN-F502	<1.0	None	---	---	---
Rm. B10 - Hallway/Corridor	Fountain (Upper/Right)	Public Access	001	HN-F503	<1.0	None	---	---	---
Rm. B107 - Classroom Bathroom	Sink	Public Access	008	HN-S509	1.7	None	---	---	---
Rm. B108 - Classroom	Sink	Public Access	015	HN-S127	7.0	See Note 8.	---	---	---
Rm. B119L - Hallway/Corridor	Fountain	Public Access	016	HN-F605	<1.0	None	---	---	---
Rm. B119A - Hallway/Corridor	Fountain (Upper/Left)	Public Access	007	HN-F504	<1.0	None	---	---	---
Rm. B119A - Hallway/Corridor	Fountain (Lower/Right)	Public Access	006	HN-F505	<1.0	None	---	---	---
Rm. B140 - Office	Main Sink	Secured - SCSD Staff Only	009	HN-S510	<1.0	None	---	---	---
Rm. B141 - Parent/Conference Room	Sink	Public Access	010	HN-S714	2.1	None	---	---	---
Rm. B119A - Hallway/Corridor	Fountain (Lower/Right)	Public Access	014	HN-F707	<1.0	None	---	---	---
Rm. B119A - Hallway/Corridor	Fountain (Sensor)	Public Access	013	HN-F707A	<1.0	None	---	---	---

## SYRACUSE CITY SCHOOL DISTRICT HUNTINGTON PK- GRADE 8 SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	07/28/23 RESULTS (ppb)	07/28/23 ACTIONS	LAB RE-SAMPLE I.D. No.	03/27/24 RE-SAMPLE RESULTS (ppb)	03/27/24 RE-SAMPLE ACTIONS
Rm. B119A - Hallway/Corridor	Fountain (Upper/Left)	Public Access	012	HN-F706	<1.0	None	---	---	---
Rm. B142 - Nurse's Room	Sink	Public Access	011	HN-S110	3.6	None	---	---	---
Rm. B207 - Classroom	Sink	Public Access	026	HN-S129B	1.2	None	---	---	---
Rm. B236 - Hallway/Corridor	Fountain	Public Access	022	HN-F704	<1.0	None	---	---	---
Rm. B236 - Hallway/Corridor	Fountain	Public Access	023	HN-F705A	<1.0	None	---	---	---
Rm. B236 - Hallway/Corridor	Fountain	Public Access	025	HN-F703	<1.0	None	---	---	---
Rm. B236 - Hallway/Corridor	Fountain	Public Access	024	HN-F702	<1.0	None	---	---	---
Rm. B239 - Hallway/Corridor	Fountain	Public Access	027	HN-F700	<1.0	None	---	---	---
Rm. B239 - Hallway/Corridor	Fountain	Public Access	028	HN-F701	<1.0	None	---	---	---
Rm. A210 - Hallway/Corridor	Fountain	Public Access	020	HN-F2000	<1.0	None	---	---	---
Rm. A210 - Hallway/Corridor	Fountain	Public Access	021	HN-F2001	<1.0	None	---	---	---

Notes: [July 28, 2023 Event]

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-008.
2. Water samples analyzed By: Pace Analytical Services, LLC - Pace Project No. 70264929.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture repaired by SCSD.
7. Fixture removed and replaced by SCSD.
8. Fixture signed by SCSD. No further action required.

Notes: [March 27, 2024 Event]

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-008.
2. Water samples analyzed By: Pace Analytical Services, LLC - Pace Project No. 70295107.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.