

**SYRACUSE CITY SCHOOL DISTRICT**  
**SEYMOUR DUAL LANGUAGE ACADEMY SCHOOL PK-GRADE 5**

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE ID No.	TDK SAMPLE ID No.	02/27/20 RESULTS (ppb)	02/27/20 ORIGINAL ACTIONS	08/08/20 RESULTS (ppb)	08/08/20 RE- SAMPLE ACTIONS	11/04/20 RESULTS (ppb)	11/04/20 RE- SAMPLE ACTIONS
Rm. 109 - Classroom	Sink	Public Access	055	SR-S317	2.0	None	---	---	---	---
Rm. 114 - Classroom	Sink	Public Access	037	SR-S329	5.4	None	---	---	---	---
Rm. 114 - Classroom	Fountain	Public Access	035	SR-F304	<1.0	None	---	---	---	---
Rm. 114A - Classroom Bathroom	Sink	Public Access	036	SR-S328	<1.0	None	---	---	---	---
Rm. 115 - Classroom	Sink	Public Access	031	SR-S217	<1.0	None	---	---	---	---
Rm. 115 - Classroom	Fountain	Public Access	029	SR-F204	<1.0	None	---	---	---	---
Rm. 115B - Classroom Bathroom	Sink	Public Access	030	SR-S216	11.1	None	---	---	---	---
Rm. 116 - Classroom	Sink	Public Access	022	SR-S215	10.9	None	---	---	---	---
Rm. 116 - Classroom	Fountain	Public Access	020	SR-F203	1.7	None	---	---	---	---
Rm. 116B - Classroom Bathroom	Sink	Public Access	021	SR-S214	<1.0	None	---	---	---	---
Rm. 117 - Classroom	Sink	Public Access	025/008	SR-S208	44.6	See Note 6	2.8	None	---	---
Rm. 117 - Classroom	Fountain	Public Access	024	SR-F202	1.1	None	---	---	---	---
Rm. 117A - Classroom Bathroom	Sink	Public Access	027	SR-S207	1.4	None	---	---	---	---
Rm. 118A - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	009	SR-S209	<1.0	None	---	---	---	---
Rm. 119 - Classroom	Sink	Public Access	056	SR-S204	<1.0	None	---	---	---	---
Rm. 119 - Classroom	Fountain	Public Access	057	SR-F201	<1.0	None	---	---	---	---
Rm. 123 - Hallway/Corridor	Fountain	Public Access	002	SR-F200	<1.0	None	---	---	---	---
Rm. 129 - Classroom Bathroom	Sink	Public Access	058	SR-S205	<1.0	None	---	---	---	---
Rm. 133 - Gym Staff Bathroom	Sink	Secured - SCSD Staff Only	054	SR-S206	<1.0	None	---	---	---	---
Rm. 137 - Audio / Visual	Sink	Public Access	001	SR-A	<1.0	None	---	---	---	---
Rm. 142 - Girl's Bathroom	Sink	Public Access	003/006	SR-S202	31.0	See Note 6	1.2	None	---	---
Rm. 142 - Girl's Bathroom	Sink	Public Access	004/007	SR-S203	21.4	See Note 6	2.9	None	---	---
Rm. 143 - Boy's Bathroom	Sink	Public Access	005	SR-S201	<1.0	None	---	---	---	---
Rm. 156 - Hallway/Corridor	Fountain	Public Access	046	SR-F303	<1.0	None	---	---	---	---
Rm. 157 - Girl's Bathroom	Sink	Public Access	049	SR-S321	1.2	None	---	---	---	---
Rm. 157 - Girl's Bathroom	Sink	Public Access	050	SR-S322	14.7	None	---	---	---	---
Rm. 158 - Boy's Bathroom	Sink	Public Access	051	SR-S318	1.5	None	---	---	---	---
Rm. 158 - Boy's Bathroom	Sink	Public Access	052/001	SR-S319	178.0	See Note 6	1.5	None	---	---
Rm. 158 - Boy's Bathroom	Sink	Public Access	053/002	SR-S320	16.8	See Note 6	1.5	None	---	---
Rm. 159 - Office Bathroom	Sink	Secured - SCSD Staff Only	047	SR-S324	<1.0	None	---	---	---	---

**SYRACUSE CITY SCHOOL DISTRICT**  
**SEYMOUR DUAL LANGUAGE ACADEMY SCHOOL PK-GRADE 5**

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE ID No.	TDK SAMPLE ID No.	02/27/20 RESULTS (ppb)	02/27/20 ORIGINAL ACTIONS	08/08/20 RESULTS (ppb)	08/08/20 RE- SAMPLE ACTIONS	11/04/20 RESULTS (ppb)	11/04/20 RE- SAMPLE ACTIONS
Rm. 160A - Office Bathroom	Sink	Secured - SCSD Staff Only	048	SR-S323	<1.0	None	---	---	---	---
Rm. 174 - Nurse's Bathroom	Sink	Public Access	041/003	SR-S327	29.9	See Note 6	3.0	None	---	---
Rm. 175 - Exam Room	Sink	Public Access	043	SR-S326	<1.0	None	---	---	---	---
Rm. 176 - Cafeteria	Fountain	Public Access	014	SR-F305	<1.0	None	---	---	---	---
Rm. 178 - Kitchen	Cooker Spray	Secured - SCSD Staff Only	017/004	SR-B	42.9	See Note 7	63.2	See Note 6	2.9	None
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	011/005	SR-S210	30.2	See Note 6	2.6	---	---	---
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	012	SR-S211	1.3	None	---	---	---	---
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	013	SR-S212	<1.0	None	---	---	---	---
Rm. 178 - Kitchen	Sink	Secured - SCSD Staff Only	015	SR-S213	<1.0	None	---	---	---	---
Rm. 182 - Staff Bathroom	Sink	Secured - SCSD Staff Only	045	SR-S325	<1.0	None	---	---	---	---
Rm. 216 - Classroom Bathroom	Sink	Public Access	039	SR-S312	5.6	None	---	---	---	---
Rm. 221 - Teacher's Lounge	Sink	Secured - SCSD Staff Only	040	SR-S315	2.6	None	---	---	---	---
Rm. 221B - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	042	SR-S313	1.6	None	---	---	---	---
Rm. 221C - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	044	SR-S314	2.2	None	---	---	---	---
Rm. 221G - Hallway/Vestibule	Fountain	Public Access	032	SR-F302	<1.0	None	---	---	---	---
Rm. 221G - Hallway/Vestibule	Sink	Public Access	033	SR-S307	6.4	None	---	---	---	---
Rm. 221G - Hallway/Vestibule	Sink	Public Access	034	SR-S308	13.4	None	---	---	---	---
Rm. 222A - Classroom	Sink	Public Access	038	SR-S309	<1.0	None	---	---	---	---
Rm. 227 - Art Room	Sink	Public Access	028	SR-S310	<1.0	None	---	---	---	---
Rm. 227 - Art Room	Sink	Public Access	026	SR-S311	1.1	None	---	---	---	---
Rm. 232 - Hallway/Corridor	Fountain	Public Access	016	SR-F301	<1.0	None	---	---	---	---
Rm. 242 - Girl's Bathroom	Sink	Public Access	018	SR-S304	<1.0	None	---	---	---	---
Rm. 242 - Girl's Bathroom	Sink	Public Access	019	SR-S305	<1.0	None	---	---	---	---
Rm. 242 - Girl's Bathroom	Sink	Public Access	023	SR-S306	<1.0	None	---	---	---	---
Rm. 245 - Boy's Bathroom	Sink	Public Access	007	SR-S301	4.2	None	---	---	---	---
Rm. 245 - Boy's Bathroom	Sink	Public Access	008	SR-S302	2.6	None	---	---	---	---
Rm. 245 - Boy's Bathroom	Sink	Public Access	010	SR-S303	8.8	None	---	---	---	---
Rm. 251 - Staff Bathroom	Sink	Secured - SCSD Staff Only	006	SR-S316	1.8	None	---	---	---	---

**SYRACUSE CITY SCHOOL DISTRICT**  
**SEYMOUR DUAL LANGUAGE ACADEMY SCHOOL PK-GRADE 5**

Original Sample Notes [February 27, 2020 Event]:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-016
2. Water samples analyzed By: Pace Analytical Services, LLC - Pace Project No. 70123403
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture removed, replaced and resampled.
7. In-line filter installed by SCSD.

Re-Sample Notes [August 8, 2020 Event]:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-016
2. Water samples analyzed By: Pace Analytical Services, LLC - Pace Project No. 70141474
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Remediation performed by SCSD.

Re-Sample Notes [November 4, 2020 Event]:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-016
2. Water samples analyzed By: Pace Analytical Services, LLC - Pace Project No. 70152547
3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.